

PT INSPEKTORAN ENERGI TERPADU
SOLUSI ENERGI SURET

Personnel In Attendance

Mangrang: Denny Jeremia, Riswan

Customer

PT DOWELL ANADRILL SCHLUMBERGER

Date

Period

Jan-24

Contract/PO Non

Our Ref

Day Rate

Rig / Well

Manggar Base

Form No

| Billing Date | Rig / Loc* | Time* | ACTIVITY | BILLING | | | | |
|----------------------|--------------|---------------|---|-------------|-----------------------------|-------|---------|----------------------------------|
| | | | | Hour's | WO Number | BOBID | Segment | Company Representative Signature |
| 20-Jan-24 | Manggar Base | 08.00 - 22.30 | Lifting Sub- Lift Sub, >=6"OD, Steel - 5 1/2-FHP, RIB11-311 - Inspection | 13,5 | To Be Created | | DNM | |
| | | | Lifting Sub- Lift Sub, >=6"OD, Steel - 4 1/2-FHP, RIB11-230 - Inspection | | To Be Created | | | |
| | | | Lifting Sub- Lift Sub, >=6"OD, Steel - 5 1/2-FHP, RIB12-359-FPS - Inspection | | To Be Created | | | |
| | | | String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 17 3/8_100624 - Inspection | | To Be Created | | | |
| | | | Control Collar 46871 - Inspection | | To Be Created | | | |
| | | | Torquer 22-5098 - Inspection | | To Be Created | | | |
| | | | Torquer - PDLTG-3C PD ORBIT LOWER TORQUER ASSEMBLY - 19-1865 - Inspection | | To Be Created | | | |
| | | | Torquer 22-5092 - Inspection | | To Be Created | | | |
| | | | Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 72633 - Inspection | | To Be Created | | | |
| | | | Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3242 - Inspection | | To Be Created | | | |
| | | | Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3480 - Inspection | | To Be Created | | | |
| | | | Telescope Collar - M10 8 25 HIGH FLOW NON-IWOB COLLAR BOX X BOX, INTERNAL ALIGNMENT KEY, NO R.O.P. - G8406 - Inspection | | WCM-200124-G8406-Ex Hakuryu | | | |
| | | | ARC - ARCRD-BB - ARCRD-BB, 8 25 ARC COLLAR ASSEMBLY W/O AIM RECEIVER - 071BSSAT - Inspection | | To Be Created | | | |
| | | | MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 24177-0401 - Inspection | | WCM-200124-G8406-Ex Hakuryu | | | |
| | | | MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002900-6-1 - Inspection | | WCM-200124-G8406-Ex Hakuryu | | | |
| | | | MSSB - CROSSOVER, M10, 5-1/2 IF PIN X 6-5/8 FH PIN - BKS 24464-0102 - Inspection | | To Be Created | | | |
| | | | Flood Valve FVP6-RIB8 - Inspection | | To Be Created | | | |
| TOTAL (hours) | | | | 13,5 | | | | |

* If Applicable

Mangrang: Denny Jeremia, Riswan
Personnel In Attendance

Mangrang
ISP Inspector

SLB Maintenance Technician

Digitally signed by Adi Rahmadita
DN: CN=Adi Rahmadita, E=arahmadita@slb.com, Location: slb Manggar Base
Date: 2024.01.21 14:01:58+08'00'
SLB Maintenance Supervisor