

PT. INSPEK TINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
Period:
Day Rate:
Per Diem Rate :

| |
|----------------------------------|
| Mangiring, Deny, Jeremia, Riswan |
| Jan-24 |
| |
| |

Customer: PT DOWELL ANADRILL SCHLUMBERGER ✓
Contract/ PO Non: _____
Rig / Well: Manggar Base

Date : _____
Our Ref: _____

Form No. :

| Billing Date | Rig / Loc* | Time* | ACTIVITY | BILLING | | | | |
|----------------------|----------------|---------------|---|-------------|-----------------------------|------|---------|----------------------------------|
| | | | | Hour/s | WO Number | BORG | Segment | Company Representative Signature |
| 20-Jan-24 | ✓ Manggar Base | 08.00 - 22.30 | Lifting Sub - Lift Sub, >=6"OD, Steel - 5 1/2-FHB_RIB11-311 - Inspection | 13,5 | To Be Created | | DNM | |
| OT | | | Lifting Sub - Lift Sub, >=6"OD, Steel - 4 1/2-IFP_RIB11-230 - Inspection | | To Be Created | | | |
| | | | Lifting Sub - Lift Sub, >=6"OD, Steel - 5 1/2-FHP_RIB12-359-BBS - Inspection | | To Be Created | | | |
| | | | String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 17 3/8_100824 - Inspection | | To Be Created | | | |
| | | | Control Collar 46871 - Inspection | | To Be Created | | | |
| | | | Torquer 22-5098 - Inspection | | To Be Created | | | |
| | | | Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 19-1865 - Inspection | | To Be Created | | | |
| | | | Torquer 22-5092 - Inspection | | To Be Created | | | |
| | | | Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 72633 - Inspection | | To Be Created | | | |
| | | | Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3242 - Inspection | | To Be Created | | | |
| | | | Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3480 - Inspection | | To Be Created | | | |
| | | | Telescope Collar - M10 8.25 HIGH FLOW NON-IWOB COLLAR BOX X BOX, INTERNAL ALIGNMENT KEY, NO R.O.P. - G8406 - Inspection | | WCM-200124-G8406 Ex Hakuryu | | | |
| | | | ARC - ARC8D-BB - ARC8D-BB, 8.25 ARC COLLAR ASSEMBLY W/O AIM RECEIVER - 071B5SAT - Inspection | | To Be Created | | | |
| | | | MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 24177-0401 - Inspection | | WCM-200124-G8406 Ex Hakuryu | | | |
| | | | MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002900-6-1 - Inspection | | WCM-200124-G8406 Ex Hakuryu | | | |
| | | | MSSB - CROSSOVER, M10, 5-1/2 IF PIN X 6-5/8 FH PIN - BKS 24404-0102 - Inspection | | To Be Created | | | |
| | | | Flood Valve FVP6-RIB8 - Inspection | | To Be Created | | | |
| TOTAL (hours) | | | | 13,5 | | | | |

* If Applicable

Mangiring, Deny, Jeremia, Riswan
Personnel In Attendance

Mangiring
ISP Inspector

Pami
SLB Maintenance Technician

Dwi Riyanto
SLB Maintenance Supervisor