

SUMMARY LIFTING EQUIPMENTS INSPECTION CAMPAIGN 1st NOVEMBER - JANUARY 2021
SITES : HCA SITE

No.	TIK No.	Equipment Type	Description	SWL (Ton)	LOCATION	INSPECTION DATE	PERFORMER	Color Code	Finding & Recommendation	
15										
1	1024-1	Runway Beam	Runway Beam	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found beam support I corrosion, should be clean and repainting. - Runway paint peel off, should be repainted	
2	1023-1	Runway Beam	Runway Beam	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found beam support ligh corrosion, should be clean and repainting. - Runway paint peel off, should be repainted	
3	1022-1	Runway Beam	Runway Beam	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found beam support ligh corrosion, should be clean and repainting. - Runway paint peel off, should be repainted	
4	1-1077	Runway Beam	Runway Beam	1,5	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Runway paint peel off, should be repainted	
5	1-1217	Runway Beam	Runway Beam	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found beam was slight corrosion, should be cleaning and repainting	
6	1-1212	Runway Beam	Runway Beam	0,75	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found beam was slight corrosion, should be cleaning and repainting	
7	1069-1	Beam Trolley	Right Hand pushed Trolley	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Body was found rusty, should be clean up and repainting	
8	1-1558	Beam Trolley	Beam Trolley with Chain Block	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found body chain block was peel off & slight corrosion, shall be repainting	
9	1-1074	Beam Trolley	Beam Trolley	1,5	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found trolley body peel off, shall be repainting	
10	1-1531	Beam Trolley	Beam Trolley with Chain Block	0,75	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found body chain block was peel off & slight corosion shall be clean up & repainting	
11	1-1533	Beam Trolley	Beam Trolley	3	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found trolley body peel off, shall be repainting. - Found hand chain was slight corrosion, shall be cleaning up & lubricated	
12	1-1534	Beam Trolley	Beam Trolley with Chain Block	0,75	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found body chain block was peel off & slight corrosion, shall be repainting. -Chain load was found slight & dry condition, shall be cleaning up & re lubricated	
13	1-1211	Slewing Jib Davit	Slewing Jib Davit	1	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Was found peel off at sctructure bottom, should be clean up and repainting	
14	1-1215	Slewing Jib Davit	JIB-Overbraced Structure	0,75	CPA - API Area	24 December 2020	Deny Herzaldi	Fit For Use	Found was peel off at sructure bottom, shall be clean up and repainting	
15	1-1757	Gantry	Mobile Gantry	0,5	CPA - API Plotator Area	24 December 2020	Deny Herzaldi	Fit For Use		
Personnel In Attendance		Meal	Equipment	Qty	Prepared by PT. ISP Inspector			Approved by PHM sites INS SPV		
1	Deny Herzaldi	1	Water bag 3 tonnes		Date : 24 December 2021			Date :		
2	A. Fuad K	1	Water bag 12 tonnes							
3	A. Wahyu	1	Load Cell 5 tonnes							
TOTAL		3	Load Cell 30 tonnes							
Transport	1		Wire rope tester		Deny Herzaldi			Ahmadan F / Abu Khoiri		
CRO No.					Name & Signature			Name & Signature		