PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | Mangiring, Deny, Akbar, Riswan, Rifaldi | Customer: | PT DOWELL ANADRILL SCHLUMBERGER | Date : | |
| Period: | Feb-23 | Contract/ PO Non: | | Our Ref: | |
| Day Rate: | | Rig / Well: | Manggar Base | | |
| Per Diem Rate : | | | | Form No. : | |

| Billing Date | Rig / Loc* | Time* | ACTIVITY | BILLING | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | Hour/s | WO Number | BORG | Segment | Company Representative Signature |
| 3-Feb-24 | Manggar Base | 08.00 - 22.00 | 12-1/4"" BIAS UNIT BODY, ORBIT 900 - 107467 - Inspection | 12 | WCM_PDORB9_5 February, 2024_PDBU900 | | DNM | |
| OT | | break | XOS - X-over Sub, >=6.75"OD, Non-Mag - 73ET001-15/02 - Inspection | | To Be Created | | | |
| | | time | X-Over - MSSA-AC, CROSSOVER SUB, 6.5CDR DH/NO LWD DH(6.75 M10), STAINLESS - 64446-10 - Inspection | | To Be Created | | | |
| | | 2 hrs | NM Pony Collar - Drill Collar, >=6.75"OD, Non-Mag, Straight - RIB11-183-SBDS - Inspection | | dd_tools30 January, 2024 | | | |
| | | | ARC - ARC8D-BB - ARC8D-BB, 8.25"ARC COLLAR ASSEMBLY W/O AIM RECEIVER - ZA91J5T1 - Ex Machine Shop | | WCM_AR ARC8D-BB ZA91J5T1_03Feb24 | | | |
| | | | Accelerator - JAR, ACCELERATOR - 8 OD - - DACCH05046J - Inspection | | WCD_BDT_06FEB24_ACC8000 | | | |
| | | | Float Sub - Float Sub, >=675"OD, Steel - RIB22-HMH-01 - Inspection | | dd_tools30 January, 2024 | | | |
| | | | Float Sub - Float Sub, >=6.75"OD, Steel - RIB12-451-BBS - Ex Machine Shop | | dd_tools1 February, 2024 | | | |
| | | | Bit Sub - X-over Sub, >=8"OD, Steel ; 4 1/2Reg Pin x 6 5/8 Reg Box - JOP10-BTS-003 - Inspection | | To Be Created | | | |
| | | | String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 14 1/2_3199 - Inspection | | dd_tools14 1/2_3199 | | | |
| | | | ADN Collar - ADDC-CE, AZIMUTHAL DENSITY DRILL COLLAR W/8.25 LASER HARD FACED INTGR SZR, 6-3/4" ADN - H5292-1 - Ex Machine Shop | | WCM_AR ADDC-CE H5292-1_03Feb24 | | | |
| | | | MTA - M10 TURBINE ASSEMBLY W/HEX BEARING HOUSING SHAFT, HEX HELICAL COUPLING AND HEX INPUT GEAR SHAFT - 3448 - Inspection | | To Be Created | | | |
| | | | MMA - HOUSING MMA-BD, M10 MODULATOR ASSEMBLY W/HEX PLANET CARRIER AND HEX BEARING HOUSING SHAFT - 3675 | | To Be Created | | | |
| | | | Antenna - ANTENNA ASSEMBLYSHORTHOP - SEC 6563 - Inspection | | WCD-PDET_240205-1 | | | |
| | | | Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 19-2016 - Inspection | | WCD-PDET_240205-1 | | | |
| | | | Jum Nut RIB-005 - Inspection | | To Be Created | | | |
| | | | Torquer - *OBS* PDCU-CA UPPER TORQUER - 90845 - Inspection | | WCD-PDET_240205-1 | | | |
| | | | 1 Set Motor A700M Stator - STATOR TUBE, 700OD550ID246LG THREADED - 18576 - Inspection | | A700M_06941_02Feb24 | | | |
| | | | **TOTAL (hours)** | 12 | | | | |

* If Applicable

| | | | |
|---|---|---|---|
| Mangiring, Deny, Akbar, Riswan, Rifaldi | Mangiring | | Doni Priyantoro |
| Personnel In Attendance | ISP Inspector | SLB Maintenance Technician | SLB Maintenance Supervisor |