PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance: Saftiadi, Akbar, Riswan
Period: June 2024
Day Rate:
Per Diem Rate :

Customer: PT. SMITH TOOL INDONESIA
Contract/ PO Non:
Rig / Well: Manggar Base

Date :
Our Ref:
Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
1-Jun-24	Manggar Base	17:00-22:00	Inspected of Reamer - RHINO REAMER UPPER CAP 8000 - AH51035 - 9081575-004 - (MPI Inspection), Reamer - Inner Mandrel - 10444808-002 - (MPI Inspection), Jar - CONNECTOR SUB;HJ65;HB - AJ12290- (MPI Inspection), Reamer - Catcher - AK03140 - (MPI Inspection), Reamer - Catcher Cap - AK67739 - (MPI Inspection), Reamer - Lower mandrel - 9395185-004 - (MPI Inspection), Reamer - Lower Mandrel Cap - 9530579-001 - 9395012-004 - 9395138-003 - (MPI Inspection), - (MPI Inspection), Reamer - Bore Guide sleeve - 9391769-005 - (MPI Inspection), Reamer - Activation Sleeve - 9296523-003 - 9395138-003 - (MPI Inspection), Reamer - Deactivation Outer Sleeve - 10450074-002 - 10427034-003 - (MPI Inspection), Reamer - Deactivation Inner Sleeve - 10367870-002 - 9395146-005 - (MPI Inspection)	5	WCD_BDT_06JUN24_RR8000_9150627-002		BDT	PT. SMITH TOOL INDONESIA
8-Jun-24	Manggar Base	17:00-22:00	Inspected of Reamer XC - CAM SUB 8.000 - 47430K - (MPI Inspection), Reamer XC - Lower Mandrel 8.000 - 9501348-003 - (MPI Inspection), Reamer XC - Lower Mandrel Sleeve 8.000 - AJ16189 - (MPI Inspection), Reamer XC - Valve Piston 8.000 - NA - (MPI Inspection), Reamer XC - CAM Piston / Spider CAM 8.000 - AJ28278 - (MPI Inspection), Reamer XC - Spring 8.000 - 3 (MPI Inspection), Reamer XC - CAM Mandrel 8.000 - 10412573-003 - (MPI Inspection), Reamer XC -CAM Mandrel Cap 8.000 - 10412573-003 - (MPI Inspection), Reamer XC - Coupling 8.000 - AJ04867 - (MPI Inspection), Reamer XC - Screen Sleeve 8.000 - AG08532 - (MPI Inspection), Reamer XC Ring - 8.000 - 8169040-003 - (MPI Inspection), Reamer XC Ring - 8.000 - 8780573-001 - (MPI Inspection), Reamer XC Ring Cover - 8.000 - 061802 - (MPI Inspection)	5	To Be Created		BDT	
10-Jun-24	Manggar Base	17:00-22:00	Inspected of Hydra Jar - JAR, H.E. HYDRA-JAR - 6-1/2 OD W/ SAFETY CLAMP - 40472J - (MPI Inspection), Drilling Accelarator - JAR, ACCELERATOR - 6-1/2 OD - - 11323J - (MPI Inspection)	5	WCD_BDT_11JUN24_SL1 JAR & ACC		BDT	
			TOTAL (hours)	15				

* If Applicable

Saftiadi, Akbar, Riswan
Personnel In Attendance

Saftiadi
ISP Inspector

SLB Maintenance Technician

19 JUN '24
ON BEHALF : RIDWAN S.
SLB Maintenance Supervisor