

**PT. INSEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:   
 Period:   
 Day Rate:   
 Per Diem Rate :

Customer:   
 Contract/ PO Non:   
 Rig / Well:

Date :   
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
3-Apr-24	Manggar Base	16:00-22:00	Inspected of Hydra Jar - JAR, H.E. HYDRA-JAR - 6-1/2 OD W/ SAFETY CLAMP - 04859J - SL-1 - (MPI Inspection), Lower sub - S92794 - (MPI Inspection)	6	WCD_BDT_03APR24_AP650_04859J		BDT	PT. SMITH TOOL INDONESIA
4-Apr-24	Manggar Base	16:00-22:00	Inspected of Bottom Sub - RHINO XS2 SUB ASSY - 8000/9250 - KSBD15233 - (MPI Inspection), Reamer - Top Sub - 73931H - (MPI Inspection)	6	To Be Created		BDT	
8-Apr-24	Manggar Base	16:00-23:00	Inspected of Reamer - Lower Mandrel - 10838281-3 - (MPI Inspection), Reamer - BORE GUIDE SLEEVE, 11625-16000 RHINO XS AND XS2 - 10958313-7 - (MPI Inspection), Reamer - DEACTIVATION INNER SLEEVE, 11625-17500 RHINO XS2 - 10838276-4 - (MPI Inspection), - (MPI Inspection), Reamer - ACTIVATION SLEEVE FOR 11625 RHINO XS2 - 10877756-3 - (MPI Inspection), Reamer - DEACTIVATION OUTER SLEEVE, 11625-17500 RHINO XS2 - 10838279-4 - (MPI Inspection), Reamer - Catcher Cap, 11625-17500 Rhino XS2 - 10734790-3 - (MPI Inspection), Reamer - RHINO REAMER II INNER MANDREL - (MPI Inspection), Under Reamer - CATCHER, 11625-17500 RHINO XS2 - 10838272-2 - (MPI Inspection), Reamer - Lower Mandrel Cap, 11625-17500 Rhino XS2 - 10838269-4 - (MPI Inspection), Reamer - Bottom sub - KSBD 13125 - (MPI Inspection), Reamer - Pin T20 x box 6-5/8 Reg - 97525E - (MPI Inspection),	7	WCD_BDT_08APR24_RR11625_13APR24		BDT	
TOTAL (hours)				19				

\* If Applicable

Saftiadi Akbar  
 Personnel In Attendance

Saftiadi  
 ISP Inspector

Geosha  
 SLB Maintenance Technician

April Rahmadita  
 SLB Maintenance Supervisor