

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangiring, Sarwo, Akbar, Saftiadi
 Period: Apr-23
 Day Rate:
 Per Diem Rate:

Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non:
 Rig / Well: Manggar Base

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
6-Apr-24	Manggar Base	08.00 - 24.00	X-Over RIB24-BBS-504 - Ex Machine Shop	8	To Be Created		DNM	
OT			X-Over GP 6968-6 - Ex Machine Shop		To Be Created			
			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 24368-0102 - Ex Machine Shop		To Be Created			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 25758-0102 - Inspection		WCM_060424_MLWD			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 25379-0102 - Inspection		WCM_060424_MLWD			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0001936-2-4 - Inspection		WCM_060424_MLWD			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 24427-0101 - Inspection		WCM_060424_MLWD			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002900-30-3 - Inspection		Gyrodata_02 April 24_GWD8_after backload			
			MSSB - MSSB-GC, CROSSOVER SUB, M10, 6-5/8 FH BOX X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002900-33-2 - Inspection		Gyrodata_02 April 24_GWD8_after backload			
			Telescope Collar - 8.25 M10 HF NON-IWOB COLLAR, INT. ALIGN. KEY, BOX X BOX, NO R.O.P. - SN31 - Inspection		WCM_060424_MLWD			
			Telescope Collar - M10 8.25 HIGH FLOW NON-IWOB COLLAR BOX X BOX, INTERNAL ALIGNMENT KEY, NO R.O.P. - N001315 - Inspection		WCM_060424_MLWD			
			Gyro Collar - Gyrodata Collar - 01P0001936-3-1 - Inspection		Gyrodata_02 April 24_GWD8_after backload			
			Gyro Collar - 825 Gyrodata Collar - 01P0002847-2-5 - Inspection		To Be Created			
			Telescope Collar - MDICX-BA, 6-3/4 NON-IWOB COLLAR, INT. ALIGN. KEY, BOX x BOX, NO R.O.P., P-550 - NNH0015 - Inspection		WCM_080424_MWD			
			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 25287-0101 - Inspection		WCM_080424_MWD			
			XOS - X-OVER SUB, >=6IN OD, NON-MAG - 7396-02 - Inspection		To Be Created			
			X-Over - MSSA-BC, CROSSOVER SUB, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - RIB12-478-SBDS - Inspection		WCM_080424_MWD			
			Flood Valve RIB-10 - Inspection		To Be Created			
			Flood Valve RIB-01 - Inspection		To Be Created			
			1 Set Motor A962M Stator - STATOR TUBE, 962OD78SID246LG THREADED - F96S0899 - Inspection		A962M_FP96BH1144_05Apr24			
TOTAL (hours)				8				

* If Applicable

Mangiring, Sarwo, Akbar, Saftiadi
Personnel In Attendance

Mangiring
ISP Inspector

Inar
SLB Maintenance Technician

Adi Rahmadita
SLB Maintenance Supervisor