

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET





Personnel In Attendance: Saftiadi, Akbar, Riswan
 Period: May 2024
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. SMITH TOOL INDONESIA
 Contract/ PO Non: _____
 Rig / Well: Manggar Base

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
24-May-24	Manggar Base	17:00-22:00	Inspected of CATCHER, 10.000 RHINO XS2 - 10297321-002 - (MPI Inspection), BORE GUIDE SLEEVE, 10.000 RHINO XS AND XS2 - 10297315-004 - (MPI Inspection), Reamer - LOWER MANDREL CAP, 10000-10375 RHINO XS2 - 10290861-001 - (MPI Inspection), Reamer - CATCHER CAP, 10000-10375 RHINO XS2 - 10297319-003 - (MPI Inspection), Reamer - DEACTIVATION INNER SLEEVE, 10000-10375 RHINO XS2 - 10169849-002 - (MPI Inspection), DEACTIVATION OUTER SLEEVE, 10000-10375 RHINO XS2 - 10290857-001 - (MPI Inspection), ACTIVATION SHEAR SLEEVE, 10000-10375 RHINO XS2 - 10290859-002 - (MPI Inspection), Reamer - LOWER MANDREL, 10000-10375 RHINO XS2 - 10169862-002 - (MPI Inspection), - (MPI Inspection), Reamer - Tob sub 10000 - V13048 - (MPI Inspection), Reamer - RHINO XS2 SUB ASSY - 10000/10375 - 10347059-001 - (MPI Inspection)	5	WCD_BDT_25MAY24_RR10000_XS2		BDT	PT. SMITH TOOL INDONESIA
30-May-24	Manggar Base	17:00-22:00	Inspected of Under Reamer - RHINO XS, UNDERREAMER - 8000 - 84294717-002 - 5156970-001 - (MPI Inspection), Reamer - RHINO REAMER SPRING RETAINER 8000 - 775541 - (MPI Inspection), Reamer - RHINO REAMER XS PISTON 8000 - NN - (MPI Inspection), Reamer - RHINO REAMER XS DRIVE RING 8000 - AG 57796 - (MPI Inspection), Reamer - RHINO REAMER STOP RING 8000 - NN - (MPI Inspection), DEACTIVATION OUTER SLEEVE, 10000-10375 RHINO XS2 - 10290857-001 - (MPI Inspection), Reamer - RHINO REAMER UPPER CAP 8000 - AH 51035 - 8384277-003 - (MPI Inspection), Reamer - Inner Mandrel - 287850-1 - 10444808-003 - (MPI Inspection)	5	To Be Created		BDT	
31-May-24	Manggar Base	17:00-22:00	Inspected of Under Reamer - RHINO XS, UNDERREAMER - 8000 - 9150627-002, - (MPI Inspection), Bottom Sub - RHINO XS2 SUB ASSY - 8000/9250 - KSBD15233 - (MPI Inspection), Hydra Jar - HJ650, DRIVE CYLINDER - 10834538-4 - (MPI Inspection), Top Sub - RHINO XS2 SUB ASSY - 8000/9250 - 73931H - (MPI Inspection), Reamer - RHINO REAMER SPRING RETAINER 8000 - AJ06455 - (MPI Inspection), Reamer - RHINO REAMER XS PISTON 8000 - 10376274-001 - (MPI Inspection), Reamer - RHINO REAMER XS DRIVE RING 8000 - 9144711-001 - (MPI Inspection), Reamer - RHINO REAMER STOP RING 8000 - AH98110 - (MPI Inspection)	5	WCD_BDT_06JUN24_RR8000_9150627-002		BDT	
TOTAL (hours)				15				


* If Applicable



 Saftiadi, Akbar, Riswan
 Personnel In Attendance



 Saftiadi
 ISP Inspector


 Geosha
 SLB Maintenance Technician


 19 JUN '24
 ON BEHALF: RIDWAN S.
 SLB Maintenance Supervisor