

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET




Personnel In Attendance: Mangiring, Deny, Alex, Riswan
 Period: Jan-24
 Day Rate:
 Per Diem Rate:

Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non:
 Rig / Well: Manggar Base


Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
20-Jan-24	Manggar Base	08.00 - 22.30	Lifting Sub - Lift Sub, >=6"OD, Steel - 5 1/2-FHB_RIB11-311 - Inspection	13,5	To Be Created		DNM	
OT			Lifting Sub - Lift Sub, >=6"OD, Steel - 4 1/2-IFP_RIB11-230 - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=6"OD, Steel - 5 1/2-FHP_RIB12-359-BBS - Inspection		To Be Created			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 17 3/8_100824 - Inspection		To Be Created			
			Control Collar 46871 - Inspection		To Be Created			
			Torquer 22-5098 - Inspection		To Be Created			
			Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 19-1865 - Inspection		To Be Created			
			Torquer 22-5092 - Inspection		To Be Created			
			Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 72633 - Inspection		To Be Created			
			Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3242 - Inspection		To Be Created			
			Antenna - ANTENNA ASSEMBLY SHORTHOP - SEC3480 - Inspection		To Be Created			
			Telescope Collar - M10 8.25 HIGH FLOW NON-JWOB COLLAR BOX X BOX, INTERNAL ALIGNMENT KEY, NO R.O.P. - G8406 - Inspection		WCM-200124-G8406 Ex Hakuryu			
			ARC - ARC8D-BB - ARC8D-BB, 8.25 ARC COLLAR ASSEMBLY W/O AIM RECEIVER - 071B5SAT - Inspection		To Be Created			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - BKS 24177-0401 - Inspection		WCM-200124-G8406 Ex Hakuryu			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/ 8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002900-6-1 - Inspection		WCM-200124-G8406 Ex Hakuryu			
			MSSB - CROSSOVER, M10, 5-1/2 IF PIN X 6-5/8 FH PIN - BKS 24404-0102 - Inspection		To Be Created			
			Flood Valve FVP6-RIB8 - Inspection		To Be Created			
TOTAL (hours)				13,5				

* If Applicable


 Mangiring, Deny, Alex, Riswan
 Personnel In Attendance


 Mangiring
 ISP Inspector


 SLB Maintenance Technician

21/01/24

SLB Maintenance Supervisor