

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
14-Mar-24	Manggar Base	16:00-24:00	Inspected of 1 Set AP Jar 6.5" - 86146 H - (MPI Inspection)	8	To Be Created		BDT	PT. SMITH TOOL INDONESIA
15-Mar-24	Manggar Base	16:00-22:00	Inspected of Reamer - RHINO REAMER INNER MANDREL 14.250" - 10091683-004 - (MPI Inspection), Reamer - Lower Mandrel Cap" - 10207442-005 - (MPI Inspection), Reamer 14.250"- Spring Retainer - 10187172-011 - (MPI Inspection), Drive Ring - 9501169-004 - (MPI Inspection), Reamer - STOP RING 14250 - 16000 RHINO REAMER II - 9501171-012 - (MPI Inspection), Reamer - Ball Guide Sleeve - 40720300 - (MPI Inspection), Piston - 10187440-007 - (MPI Inspection)	6	To Be Created		BDT	
16-Mar-24	Manggar Base	08:00-22:00	Inspected of Under Reamer - Body RHINO XS, UNDERREAMER 14.250"- 10386103-002 / 10171671-001 - (MPI Inspection)	14	To Be Created		BDT	
			Inspected of Under Reamer - Body RHINO XS, UNDERREAMER 14.250"- 10386103-002 / 10171671-001 - (MPI Inspection), Reamer XM - Lower Cam Housing - SN 32- (MPI Inspection), Reamer XM - Lower Mandrel - SN 17 - (MPI Inspection), Reamer XM - Lower Mandrel CAP - 10876208 - (MPI Inspection), Reamer XM - Centering Sleeve - SN 17 - (MPI Inspection), Reamer XM - Shear Ring Housing - 22 WBM 034-02-002 - (MPI Inspection), Reamer XM - Upper Cam Mandrel - SN 25 - (MPI Inspection), Reamer XM - Lower Cam Mandrel - SN 29 - (MPI Inspection), Reamer XM - Lower Mandrel Sleeve - 4582842685-2-6 - (MPI Inspection), Reamer XM - Spider Cam - SN 15 - (MPI Inspection), Reamer XM - Tension Sleeve - SN 10 - (MPI Inspection), Reamer XM - Valve Piston - SN 3 - (MPI Inspection), Reamer XM - Lower Seal Mandrel - SN 18 - (MPI Inspection)					
			Inspected of Reamer XM - Spring - 4582176019-1-11 - (MPI Inspection), Reamer XM - SN 4 - (MPI Inspection), Reamer XM - SN 24 - (MPI Inspection), Reamer XM - Filter - NN - (MPI Inspection), Reamer XM - CAM SUB - 5000199047-3 - (MPI Inspection), Reamer XM - Valve Piston Coupler - 10838797-2 - (MPI Inspection), Reamer XM - Torque Coupler - SN 9 - (MPI Inspection), Reamer XM - Centralizer Spacer - SN 03 - (MPI Inspection), Reamer XM - Spring Spacer - SN 01 - (MPI Inspection), Reamer XM - Spacer Ring - SN 3 - (MPI Inspection), Reamer XM - Rotating Cam Stop - SN 24 - (MPI Inspection), Reamer XM - SN 10825714 - (MPI Inspection)					
TOTAL (hours)				28				

Saftiadi, Akbar, Riswan
 Personnel In Attendance

Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

Dwi Riyantoso
 SLB Maintenance Supervisor

* If Applicable