

Discussion of Service Quality Issue at SLB

02:30:59

Take control Pop out Chat People Raise React View Notes Apps More Camera Mic Share Leave

AutoSave OFF Sampul 2.v Search Rony Prayitno

File Home Insert Draw Page Layout Formulas Data Review View Help

Clipboard Font Alignment Number Styles Cells Editing Add-ins

A	B	C	D	E	F	G
3	Recommended for MPI Fluorescent instead of white contrast	PRS	OIB, KAL & DURU	SLB need to advice the usage of MPI Fluorescent in term of equipment to be inspected and location as for Tubular inspection than MPI Fluorescent for Full Body Inspection. For lifting equipment need to consider if the inspection need to be carried out on site which will requires additional tools to inspect MPI Fluorescent such as dark room		
4	Wrong S/N in report.	RP	OIB, KAL & DURU	1. S/N was assigned by SLB due to project need	1. If required SLB need to confirm we will not entertaint the swap S/N due to project need	
5	Need procedure or Working Instruction to do dog plate and drive plate inspection	RP	OIB & KAL	2. S/N was not given or clearly stated within WO/Base	2. Within WO shall be stated S/N since on the equipment there is a lot information may be interpreted as S/N	
5				Current practice only to do MPI with acceptance and rejection criteria to detect crack only. SLB need to advice code & standard or internal SLB Procedure for details inspection and acceptance and rejection criteria for procedure references		

PK Pambudhi K

RP Rony Prayitno

YF Yonas Febrian

DM Doharmin ...

AS Achmad Sa... View all



Windows taskbar with Search, task icons, and system tray showing 6:13 PM 2/6/2024

