

## **DEFECT REPORT**



Name	Mangara Tua Immanuel Sianturi	Date	14 August 2023
Employee No.	ISP22314	Time	15.00
Position	INSPECTOR	Location	SLB DURI
Control No:	*Leave this field empty, to be filled by the store person		

Description of Equipment						
Description	Serial Number / Asset Number	Type / Model	Manufacturer			
AC YOKE	-	29675	CONTOUR PROBE			
Description and cause of defect						

Tidak dapat berfungsi.





Treatment

State the correction to stop the occurrence and recommendation to prevent recurrence

Data of Chaoking	Remedial Action Require / Taken			
Date of Checking	Repair	Replace	Disposal/Scrap	
14 Aug 2023				

Reported by	Reviewed by	Approved By :	Action by:
MA			
Name: Mangara	Name:	Name:	Name:
Date : 14 Aug 2023	Date :	Date :	Date :

