

# PT. INSPEKTINDO SINERGI PERSADA

## SERVICES TIME SHEET



Personnel In Attendance: Hajili, Petrus, and Team  
 Period: July 21 - Aug 20, 2022  
 Day Rate: \_\_\_\_\_  
 Per Diem Rate: \_\_\_\_\_

Customer: PETRONAS CARIGALI  
 Contract/ PO No: \_\_\_\_\_  
 Rig / Well: LAMONGAN SHOREBASE

Date: 21-Aug-22  
 Our Ref: \_\_\_\_\_

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
29	18-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, FLD, Internal Cleaning Internal Coating, Re-Dope, UT Spot Check. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 10 FT SAP. 51036580. 71 Jts. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 15 FT SAP. 51036581. 19 Jts. Blast Joint 4-1/2" 12.60 PPF L80 TSH-Blue PXB 20FT SAP. 51070658. 1 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP PXB 10 FT SAP. 51036583. 15 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 12 FT SAP. 50903128. 2 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP PXP 6 FT SAP. 51070780. 2 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 8 FT SAP. 50903126. 2 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 TSH-BLUE PXB 6 FT SAP. 51036582. 1 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 6 FT SAP. 50903125. 1 Jts. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 6 FT SAP. 51070775. 2 Jts	1		
30	19-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 10 FT SAP. 51036580. 71 Jts. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 15 FT SAP. 51036581. 19 Jts. Blast Joint 4-1/2" 12.60 PPF L80 TSH-Blue PXB 20FT SAP. 51070658. 1 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP PXB 10 FT SAP. 51036583. 15 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 12 FT SAP. 50903128. 2 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP PXP 6 FT SAP. 51070780. 2 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 8 FT SAP. 50903126. 2 Jts. PUP JOINT 3-1/2" 9.2 PPF L80 TSH-BLUE PXB 6 FT SAP. 51036582. 1 Jts. PUP JOINT 3-1/2" 12.70 PPF L80 HSL-APEX PXB 6 FT SAP. 50903125. 1 Jts. PUP JOINT 4-1/2" 12.60 PPF L80 TSH-BLUE PXB 6 FT SAP. 51070775. 2 Jts	1		
31	20-Aug-22	LSB	08.00 - 17.00	VBI, FLD, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. CASING 7" 29 PPF L80 VAMTOP R-3. 17 Jts SAP. 51069633. CASING 7" 26 PPF L80 TSH-BLUE R-3. 7 Jts SAP. 51036626. CASING 9-5/8" 47 PPF L80 TSH-BLUE R-3. 9 Jts SAP. 51036624.	1		
<b>TOTAL (Days)</b>					30		
<b>TOTAL (USD)</b>							
<b>GRAND TOTAL</b>							

\* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark

  
**HAJILI**  
 Personnel In Attendance

Contractor Representative

Rig Representative

  
**Parulian Yulianto**  
 Storage Supervisor  
 The Company Representative

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:	Hajili, Petrus, and Team	Customer:	PETRONAS CARIGALI	Date:	21-Aug-22
Period:	July 21 - Aug 20 ,2022	Contract/ PO No:		Our Ref:	
Day Rate:		Rig / Well:	LAMONGAN SHOREBASE		
Per Diem Rate :					

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
18	7-Aug-22	LSB	08.00 - 17.00	VBI, FLD, Cleaning Connection, VTI, Internal Cleaning / Coating, Re-Dope . TUBING 5-1/2" 17 PPF L80 TSH-MS R-3 48 Jts SAP. 51072618	1		
19	8-Aug-22	LSB	08.00 - 17.00	External Clneng, UT Spot Check, External Coating, Marking and Colour Grade Inspection. TUBING 5-1/2" 17 PPF L80 TSH-MS R-3 48 Jts SAP. 51072618	1		
20	9-Aug-22	LSB		VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 15 Jts SAP. 51071511	1		
21	10-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 15 Jts SAP. 51071511. VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. External Cleaning, External Coating Marking and Colour Grade Inspection. PUP JOINT 13-3/8" OD 68 PPF L80 BTC 6FT. SAP. NON STOCK	1		
22	11-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511, INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X DRIVE SHOE . 3 Jts SAP. 51071511	1		
23	12-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511, INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X DRIVE SHOE . 3 Jts SAP. 51071511	1		
24	13-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. External Cleaning, External Coating Marking and Colour Grade Inspection. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP SB20 4FT SAP. 51069692. 20 Jts	1		
25	14-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP SB20 6 FT SAP. 51069611. 25 Jts, PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP SB20 10 FT SAP. 51069612. 10 Jts, INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 10 Jts SAP. 51071511. INTERMEDIATE 24 " OD 1" WT X56 PUMA DF BOX UP X PIN DOWN . 5 Jts SAP. 51069652. INTERMEDIATE 24 " OD 1" WT X56 PUMA DF BOX UP X DRIVE SHOE . 1 Jts SAP. 51069652.	1		
26	15-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating, Marking and Colour Grade Inspection, PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP SB20 6 FT SAP. 51069611. 25 Jts, PUP JOINT 3-1/2" 9.2 PPF L80 VAMTOP SB20 10 FT SAP. 51069612. 10 Jts, INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 10 Jts SAP. 51071511. INTERMEDIATE 24 " OD 1" WT X56 PUMA DF BOX UP X PIN DOWN . 5 Jts SAP. 51069652. INTERMEDIATE 24 " OD 1" WT X56 PUMA DF BOX UP X DRIVE SHOE . 1 Jts SAP. 51069652.	1		
27	16-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, FLD, Internal Cleaning Internal Coating, Re-Dope, UT Spot Check. External Cleaning, External Coating Marking and Colour Grade Inspection. PUP JOINT 9-5/8" 47 PPF L80 VAM21 HT PXB 6 FT SAP. 51070765. 17 Jts. PUP JOINT 9-5/8" 47 PPF L80 VAMTOP PXB 6 FT SAP. 51069668. 1 Jts PUP JOINT 9-5/8" 47 PPF L80 VAM21 HT PXB 10 FT SAP. 51070766. 7 Jts. PUP JOINT 9-5/8" 47 PPF L80 VAM21 HT PXP 10 FT SAP. 51070768. 2 Jts. CROSS OVER 9-5/8" 47 PPF L80 VAM21 PIN X TSH-BLUE BOX 15FT 3 Jts SAP. 51072698. CROSS OVER 9-5/8" 47 PPF L80 VAM21 BOX X TSH-BLUE PIN 15FT 3 Jts SAP. 51072699. CROSS OVER 9-5/8" 47 PPF L80 VAM21 BOX X TSH-BLUE PIN 10FT 1 Jts SAP. 51072699.	1		
28	17-Aug-22	LSB	08.00 - 17.00	OFF DAY (INDEPENDENT DAY)			

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:	Hajili, Petrus, and Team	Customer:	PETRONAS CARIGALI	Date:	21-Aug-22
Period:	July 21 - Aug 20, 2022	Contract/ PO No:		Our Ref:	
Day Rate:		Rig / Well:	LAMONGAN SHOREBASE		
Per Diem Rate:					

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
					Day	Mob/ Demob (USD)	Per diem (Day)
1	21-Jul-22	LSB	08.00 - 17.00	External Cleaning. UT Spot Check CASING 7 " OD 29 PPF L-80 VAMTOP R-3. 47 Jts SAP.51069633	1		
2	22-Jul-22	LSB	08.00 - 17.00	External Coating, Marking and Colour Grade Inspection CASING 7 " OD 29 PPF L-80 VAMTOP R-3. 47 Jts SAP.51069633	1		
3	23-Jul-22	LSB	08.00 - 17.00	Measurement Groove INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 20 Jts SAP. 51071511	1		
4	24-Jul-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, Internal Cleaning Internal Coating, Re-Dope. External Cleaning UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 9 Jts SAP. 51071511	1		
5	25-Jul-22	LSB	08.00 - 17.00	External Coating, Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 9 Jts SAP. 51071511	1		
6	26-Jul-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, Internal Cleaning Internal Coating, Re-Dope. External Cleaning UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 13 Jts SAP. 51071511. VBI, End Drift, Cleaning Connection, VTI, Internal Cleaning / ID Blowing Internal, Coating, Re-Dope. Assy Pup Joint With Completion Tools Various Size and Connection 10 Jts	1		
7	27-Jul-22	LSB	08.00 - 17.00	External Cleaning, UT, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 13 Jts SAP. 51071511. External Cleaning, UT, External Coating Marking and Colour Grade Inspection Assy Pup Joint With Completion Tools Various Size and Connection 10 Jts	1		
8	28-Jul-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, Internal Cleaning Internal Coating, Re-Dope. External Cleaning UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 14 Jts SAP. 51071511	1		
9	29-Jul-22	LSB	08.00 - 17.00	External Cleaning, UT, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 14 Jts SAP. 51071511.	1		
10	30-Jul-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, Internal Cleaning Internal Coating, Re-Dope. External Cleaning UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511	1		
11	31-Jul-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511.	1		
12	1-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, Internal Cleaning Internal Coating, Re-Dope. External Cleaning UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511	1		
13	2-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511.	1		
14	3-Aug-22	LSB	08.00 - 17.00	VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope, UT Spot Check. INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511	1		
15	4-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection INTERMEDIATE 24 " OD 0.750 WT X56M PUMA BOX UP X PIN DOWN R-3. 12 Jts SAP. 51071511. VBI, Cleaning Connection, VTI, Internal Cleaning, Internal Coating, Re-Dope X-OVER 9-5/8" 47 PPF TSH-BLUE PIN X NC50 BOX, X-OVER 9-5/8" 47 PPF VAM21 PIN X NC50 BOX, X-OVER 7" 26 PPF TSH-BLUE PIN X 5-1/2 FH BOX, X-OVER 7" 29 PPF VAMTOP PIN X NC50 BOX, X-OVER 13-3/8" 68 PPF BTC PIN X NC50 BOX. SAP. NON STOCK	1		
16	5-Aug-22	LSB	08.00 - 17.00	External Cleaning, External Coating Marking and Colour Grade Inspection. X-OVER 9-5/8" 47 PPF TSH-BLUE PIN X NC50 BOX, X-OVER 9-5/8" 47 PPF VAM21 PIN X NC50 BOX, X-OVER 7" 26 PPF TSH-BLUE PIN X 5-1/2 FH BOX, X-OVER 7" 29 PPF VAMTOP PIN X NC50 BOX, X-OVER 13-3/8" 68 PPF BTC PIN X NC50 BOX. SAP. NON STOCK. VBI,FLD, Cleaning Connection, VTI, Internal Cleaning / Coating, Re-Dope. CASING 18-5/8" 87.50 PPF K55 TP-QR R-3. 13 Jts SAP.51071508. PUP JOINT 18-5/8" 87.50 PPF K55 TP-QR 15 FT. 1 Jts SAP.51071509. X-OVERT 18-5/8" 87.50 PPF K55 TP-QR PIN X BTC PIN 2 Jts SAP.51072395	1		
17	6-Aug-22	LSB	08.00 - 17.00	External Clening, UT Spot Check, External Coating, Marking and Colour Grade Inspection. CASING 18-5/8" 87.50 PPF K55 TP-QR R-3. 13 Jts SAP.51071508. PUP JOINT 18-5/8" 87.50 PPF K55 TP-QR 15 FT. 1 Jts SAP.51071509. X-OVERT 18-5/8" 87.50 PPF K55 TP-QR PIN X BTC PIN 2 Jts SAP.51072395	1		