# **CURRICULUM VITAE**

Name : MUHAMMAD FADLY

Place / Date of Birth : Medan, August 17, 1984

Total Experience : 9 Years

Nationality : INDONESIA

Language Known : Indonesia,

English

Email : <u>twincute2021@gmail.com</u>

WA Number : 081381714827

### Education

► Senior High School

## **Training Course**

► Operator Radiography, by BAPETEN

### Qualification

► RT Level I (OR)



### **Work Experience**

#### **Project Assignment**

#### Technician Radiography for ALL Project.

Client : OILFILED TECHNICAL INSPECTION

Location : NSE Kuroshio 1 - Thailand Offshore

Position : RT Tech

Period : January 26, 2022 – November 9, 2022

Job Description : Radiography Testing Pipeline

Project : PTTEP, JDA Block B-17 Field Development Project (Phase5) Size

18"x20,6mmWT

Client : OILFILED TECHNICAL INSPECTION

Location : NSE Kuroshio 1 - Thailand Offshore

Position : RT Tech

Period : May 1, 2021 – December 8, 2021

Job Description : Radiography X-Ray for Welder Test

Project : EPCI for AWP-39, ARTHIT Phase 3D, G1/61 Phase 1A & G2/61 Phase

1A, 2021

Client : PT. MEINDO ELANG INDAH

Location : Bintan – Kepulauan Riau

Position : RT - I

Period : September 10, 2020 – April 25, 2021

Job Description : Inspection Radiografy Structure and Piping

Project : Bukit Tua and Jawa-1

Client : PT. H-TECH OILFIELD EQUIPMENT

Location : Kabil - Batam

Position : RT - I

Period : April 27, 2019 – April 10, 2020

Job Description : Radiographic Inspection on Pipe Connector Tubular

Project : BP ANGOLA Ø24" and 22"

Client : PT. H-TECH OILFIELD EQUIPMENT

Location : Kabil - Batam

Position : RT - I

Period : August 1, 2018 – February 15, 2019

Job Description : Radiographic Inspection on Pipe Connector Tubular

Project : TOTAL MAURITANIA & SENEGAL Ø36''and 20''

Client : PT.MEINDO ELANG INDAH

Location : Pematang Lumut - Jambi

Position : RT - I

Period : May 19, 2016 – June 10, 2016

Job Description : Radiographic Inspection Pipe 6" Thk 7.92mm

Project : EPCI for Betara Complex Development – Petrochina

Client : PT. WASCO ENGINEERING INDONESIA

Location : Tanjung Uncang - Batam

Position : RT - I

Period : November 5, 2015 – May 18, 2016

Job Description : Radiographic Inspection

Project : YINSON E-House (Kongberg) and PGM Ghana OCTP Development

Client : PT. SURVEYOR INDONESIA

Location : Batu Ampar - Batam

Position : RT Tech

Period : September 14, 2015 – October 9, 2015

Job Description : Supporting Radiographic X-Ray Inspection

Project : TOYO KANETSU

Client : PT. WASCO ENGINEERING INDONESIA

Location : Tanjung Uncang - Batam

Position : RT Level I

Period : September 11, 2015 – January 4, 2016

Job Description : Radiographic Inspection on Structure

Project : YINSON Project OCTP E-House

Client : OILFIELD TECHNICAL INSPECTION

Location : Offshore – Sapura 3000 – Brunnei Darussalam

Position : RT Tech

Period : June 23, 2015 – Augstus 23, 2015

Job Description : Radiographic Inspection on Pipeline Ø18" Thk 17,3mm

Project : Cladding Total Maharajalela South Project

Client : PT. H-TECH OILFIELD EQUIPMENT

Location : Kabil - Batam

Position : RT - I

Period : April 14, 2015 – June 2, 2015

Job Description : Radiographic Inspection on Pipe Connector Tubular

Project : BP Egypt, Shinba (Ikan Paus), Sumitomo (Inpex Australia Lot 4)

Client : PT. WASCO ENGINEERING INDONESIA

Location : Tanjung Uncang - Batam

Position : RT Level I

Period : January 1, 2015 – November 3, 2015

Job Description : Radiographic Inspection on Pressure Vessel And Piping

Project : MOHO NORD and TEN MODULE, MV-27

Client : PT. WASCO ENGINEERING INDONESIA

Location : Tanjung Uncang - Batam

Position : RT Level I

Period : December 9, 2014 – December 31, 2014

Job Description : Radiographic Inspection on Pressure Vessel And Piping

Project : MOHO NORD and TEN MODULE

Client : OILFIELD TECHNICAL INSPECTION

Location : Thailand - Offshore

Position : RT Technician

Period : September 6, 2014 – November 15,2014

Job Description : Radiographic X-Ray crawler

Client : OILFIELD TECHNICAL INSPECTION

Location : Thailand - Offshore

Position : RT Technician

Period : June 6, 2014 – July 20, 2014

Job Description : Radiographic X-Ray crawler

Client : OILFIELD TECHNICAL INSPECTION

Location : Thailand - Offshore

Position : RT Technician

Period : January 1, 2014 – June 05, 2014

Job Description : Radiographic X-Ray on Welder Qualification Testing

Client : OILFIELD TECHNICAL INSPECTION

Location : Nippon Steel - Batam

Position : RT Technician

Period : August 28, 2013 – December 31, 2013

Job Description : Radiographic X-Ray on Welder QualificationTesting

Client : PT. HI-TEK INDO MULIA

Location : Batam

Position : RT Technician

Period : July 18, 2013 – August 27, 2013

Job Description : Support PT. Hi-Tek Indo Mulia on Radiography

Project : PT. PROFAB and PT. DSAW

Client : PT. WASCO ENGINEERING INDONESIA

Location : Tanjung Uncang, Batam

Position : RT - I

Period : July 18, 2013 – August 27, 2013

Job Description : Radiography Inspection on Pressure Vessel GLD 15/16

Project : Chevron

Client : PT. ROTARY ENGINEERING INDONESIA

Location : Tanjung Uncang, Batam

Position : RT - I

Period : July 18, 2013 – August 27, 2013

Job Description : Radiography Inspection

Project : Evonik Me5

Client : OILFIELD TECHNICAL INSPECTION ( SAIPEM )

Location : Vietnam – Offshore

Position : RT Technician

Period : March, 2013 – July 14, 2013

Job Description : Radiographic X-Ray Crawler pipe line

Project : Bien Dong Project

Client : TECHNIC OFFSHORE JAYA, PT

Location : Sekupang, Batam

Position : RT - I

Period : December, 2012 – February, 2013

Job Description : Radiographic Inspection Piping

Client : HANSA ENGINEERING INDONESIA, PT

Location : Tanjung Uncang, Batam

Position : RT - I

Period : September, 2012 - November, 2012

Job Description : Radiographic Inspection Tubular Tubing

Client : DUA UTAMA JAYA, PT

Location : Batu Ampar – Batam

Position : RT - I

Period : July, 2012 – August, 2012

Job Description : Radiographic Inpection WQT Pipe and Plate

Client : VETCO GRAY INDONESIA, PT

Location : Batu Ampar – Batam

Position : RT - I

Period : May, 2012- June, 2012

Job Description : Radiographic Inspection Tubular Tubing

Client : TRANSALINDO EKA PERSADA, PT

Location : Batu Ampar – Batam

Position : Tech

Period : October, 2010 - April, 2011

Job Description : Radiographic Inspection Piping and Pressure Vessel

Client : VETCO GRAY INDONESIA, PT

Location : Batu Ampar – Batam

Position : Tech

Period : January, 2010- July, 2010

Job Description : Radiographic Inspection Tubular Tubing