

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hours	WO Number	BORG	Segment	Company Representative Signature
20-Feb-24	Manggar Base	18.00 - 23.00	Sleeve Stab 204061 - Inspection	5	To Be Created		DNM	
OT			MSSB - MSSB-MC, CROSSOVER, 5-1/2 IF PIN X 6-5/8 FH PIN, SST - BKS 19466-0103 - Inspection		WCM_200224_ARC8 ZA181T12			
			ARC - DRILL COLLAR ASSY, 8.25 ARC W/O AIM RECEIVER - ZA181T12 - Inspection ✓		WCM_200224_ARC8 ZA181T12			
			Blank Sleeve NN - Inspection		To Be Created			
			Stator 962 - S962783.7-DTX-STD-COUNTER BORED TUBE - F96S1153 - Inspection ✓		S962M_FS96B0143_20Feb24			
			Rotor Coupling NN - Inspection		To Be Created			
TOTAL (hours)				5				

* If Applicable

Mangiring, Sarwo, Riswan, Deny
 Personnel In Attendance

Mangiring
 ISP Inspector

SLB Maintenance Technician

Doni Riyanto
 SLB Maintenance Supervisor