PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Deny, Sarwo	Customer:	PT DOWELL ANADRILL SCHLUMBERGER	Date :	
Period:	Mar-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
6-Mar-24	Manggar Base	17.00 - 23.00	XOS - CROSSOVER, 6-5/8 REG BOX X 6-5/8 FH BOX - JOP19-BTS-7650-2 - Inspection	8	WCM_070324_Cross over		DNM	
OT			MSSB - MSSB-JC, CROSSOVER SUB, NO LWD DH (8.25 M10), STAINLESS STEEL - OVP31381 - Inspection		WCM_070324_Cross over			
			NMDC - Drill Collar, >=8"OD, Non-Mag, Straight - 79113-J - Inspection		To Be Created			
			X-Over - MSSA-EC, CROSSOVER SUB, M10, 5-1/ 2 FH PIN X 5-1/2 FH PIN,STAINLESS STEEL - RIB12-478-SBDS - Inspection		MWD-06032024-NNH0015			
			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 24177-0301 - Inspection		MWD-06032024-NNH0015			
			EXTENSION COLLAR, PDX6 - 98496 - Inspection		WCD_PDOR675-97105_240306			
			Control Collar - PDSC6-GA , 6-3/4"" SLEEVE-STAB. CU COLLAR, SLENDER ANCHOR BOLT HOLE - N9M1084 - Inspection		WCD_PDOR675-97105_240306			
			PD6 CONTROL COLLAR SLEEVE - 100398083 - JOP22-OSS-003 - Inspection		To Be Created			
			8-1/2"" BIAS UNIT BODY, ORBIT 675 - 102638 - Inspection		WCD_PDOR675-97105_240306			
			TOTAL (hours)	8				

* If Applicable

12/03/24

Mangiring, Deny, Sarwo	Mangiring		Doni Priyanto
Personnel In Attendance	ISP Inspector	SLB Maintenance Technician	SLB Maintenance Supervisor