**PT. INSPEKTINDO SINERGI PERSADA**
**SERVICES TIME SHEET**

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | Mangiring, Rifaldi, Jeremia, Sarwo, Tomanro, Akbar | Customer: | PT DOWELL ANADRILL SCHLUMBERGER | Date : | |
| Period: | May-23 | Contract/ PO Non: | | Our Ref: | |
| Day Rate: | | Rig / Well: | Manggar Base | | |
| Per Diem Rate : | | | | Form No. : | |

| Billing Date | Rig / Loc* | Time* | ACTIVITY | BILLING | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | Hours | WO Number | BORG | Segment | Company Representative Signature |
| 19-May-24 | Manggar Base | 08.00 - 21.00 | Motor Catcher Stem - 675 MOTOR CATCHER STEM, SOLID, 6-10 - FP67MC0711 - Inspection | 12 | MotorCatcherA675M_19May24 | | DNM | |
| OT | | | NMDC - Drill Collar, >=6.75"OD, Non-Mag, Straight - 33376-J - Inspection | | dd_tools;19 May, 2024 | | | |
| | | | NMDC - Drill Collar, >=6.75"OD, Non-Mag, Straight - 33377J - Inspection | | dd_tools;19 May, 2024 | | | |
| | | | Stator 675 - STATOR SW.RS120N743M.121Z12, DRU1-120RS.864 - 2112532-02 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Stator Adapter - STATOR ADAPTER, D-120RS.019 - 2018530-04 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Motor Catcher Sub - TOP SUB NC 38, DRU1-120RF.013 - 2112008-01 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Stator 675 - STATOR SW.RS120N743M.121Z12, DRU1-120RS.864 - 2112532-01 - Inspection | | Radius475_6932_18May24 | | | |
| | | | Stator Adapter - STATOR ADAPTER, D-120RS.019 - 1916590-03 - Inspection | | Radius475_6932_18May24 | | | |
| | | | Motor Catcher Sub - TOP SUB NC 38, DRU1-120RF.013 - 2112006-01 - Inspection | | Radius475_6932_18May24 | | | |
| | | | Rotor - ROTOR475, R.RS120N743 Chrome - 2112005-01 - Inspection | | Rotor475_20MAY2024_2112005-01 | | | |
| | | | Rotor - ROTOR475, R.RS120N743 Chrome - 2112005-02 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Motor Catcher Stem - CATCHER ROD, D-120RS.040 - 2112032-01 - Inspection | | Radius475_6932_18May24 | | | |
| | | | Motor Catcher Stem - CATCHER ROD, D-120RS.040 - 2112032-02 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Arc6 V8875SAT - Inspection | | To Be Created | | | |
| | | | ARC - 6.75 ARC DRILL COLLAR ASSY, W/O AIM, 30K PSI - HI562-1 - Inspection | | To Be Created | | | |
| | | | MSSA-DC - MSSA-DC, CROSSOVER, NC50 PIN X 5-1/2 FH PIN, SST - 754690 7-7 - Inspection | | To Be Created | | | |
| | | | Motor - PPAK - 6 3/4" - 475 Radius Vortex Motor D-120 - 6933 - Inspection | | Radius475_6933_18May24 | | | |
| | | | Motor - PPAK - 6 3/4" - 475 Radius Vortex Motor D-120 - 6932 - Inspection | | Radius475_6932_18May24 | | | |
| | | | **TOTAL (hours)** | **12** | | | | |

* If Applicable

21/05/24

| Mangiring, Rifaldi, Jeremia, Sarwo, Tomanro, Akbar | Mangiring | | |
|---|---|---|---|
| Personnel In Attendance | ISP Inspector | SLB Maintenance Technician | SLB Maintenance Supervisor |