

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

Mangiring, Sarwo, Akbar, Riswan, Saftiadi

Customer:

PT DOWELL ANADRILL SCHLUMBERGER

Date :

Period:

Dec-23

Contract/ PO Non:

Our Ref:

Day Rate:

Rig / Well:

Manggar Base

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
13-Dec-23	Manggar Base	18.00 - 23.00	MUD MOTOR SLEEVE - S962M, STAB, SLEEVE, STR, 17.250 GA - OSS23-01204 - Inspection	5	SleeveStabilizer17.25HS_7dec23		DNM	 Egan A
OT			Bearing Nut - S962M, BEARING, RADIAL, LOWER, OUTER - FS96RB1695 - Inspection		S962M_FS96B0142_13Dec23			
			Rotor Coupling - S962M, SOCKET, TOP, HIGH TORQUE - FS96CU0407 - Inspection		S962M_FS96B0142_13Dec23			
			Upper Rotating - BEARING, RADIAL, UPPER, INNER, S962M - FS96RB0795 - Inspection		S962M_FS96B0142_13Dec23			
			Lower Rotating Radial Bearing - S962M, BEARING, RADIAL, LOWER, INNER - FS96RB0901 - Inspection		S962M_FS96B0142_13Dec23			
			Shaft Coupling - *OBS, USE 103006004* S962M, SOCKET, INTEGRATED, HIGH TORQUE - FS96C10426 - Inspection		S962M_FS96B0142_13Dec23			
			Transmission Shaft - S962M, TIE ROD, BOOTED, HT - FS96TR0422 - Inspection		S962M_FS96B0142_13Dec23			
			Stator Adapter - S962M, HSG, STATOR ADAPTER, ABH, SRG - FS96AU0301 - Inspection		S962M_FS96B0142_13Dec23			
			Driveshaft - DRIVESHAFT, BOX, 7-5/8 API REG, S962M - FS96DS0359 - Inspection		S962M_FS96B0142_13Dec23			
			Offset Housing - S962M, HOUSING, OFFSET, ABH - FS96AL0322 - Inspection		S962M_FS96B0142_13Dec23			
			Adjusting Ring - S962M, RING, ADJUSTMENT - FS96AR0325 - Inspection		S962M_FS96B0142_13Dec23			
			Splined Mandrel - COUPLING, ADJUSTMENT, ABH, 0-3 DEG, S962M - FS96AC0340 - Inspection		S962M_FS96B0142_13Dec23			
			Top Seal NN - Inspection		To Be Created			
			Bottom Seal NN - Inspection		To Be Created			
			Upper Stationary Bearing - BEARING, RADIAL, UPPER, OUTER, S962M - FS96RB0805 - Inspection		S962M_FS96B0142_13Dec23			
			Lifting Sub - Lift Sub, >=6"OD, Steel - 4 1/2-IFP_RIB11-228 - Inspection		To Be Created			
			MTA Housing 917 - Inspection		To Be Created			
			Bearing Housing - S962M, HOUSING, BEARING, SLEEVE - FS96BH0384 - Inspection		S962M_FS96B0142_13Dec23			
<b>TOTAL (hours)</b>				<b>5</b>				

\* If Applicable

Mangiring, Sarwo, Akbar, Riswan, Saftiadi  
Personnel In Attendance

Mangiring  
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor