

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:   
 Period:   
 Day Rate:   
 Per Diem Rate:

Customer:   
 Contract/ PO Non:   
 Rig / Well:

Date:   
 Our Ref:   
 Form No. :


Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
7-Jan-24	Manggar Base	08:00-22:30	Inspected of 1 set Rhino reamer 8000 - 9291626-001- (MPI Inspection), Bullnose - AH34544 - (MPI Inspection), Bullnose - AH73041 - (MPI Inspection), Bit sub - RIB12-464 BBS. - (MPI Inspection), Bit sub - 83542J - (MPI Inspection),	12,5	WCD_BDT_06JAN24_BULLNOS E & XOVER		BDT	PT. SMITH TOOL INDONESIA
8-Jan-24	Manggar Base	17:00-22:30	Inspected of Tob sub Rhino Reamer 16.000 - 33078J - (MPI Inspection), Bottom sub Rhino 16.000 - 99367HA- (MPI Inspection) , and Cleaning Body DTU 16.000..	5,5	To Be Created		BDT	
9-Jan-24	Manggar Base	17:00-22:30	Inspected of 1 set Hydraquacker 6,5" - 47023 H - (MPI Inspection)	5,5	WCD_BDT_09JAN24_HQ650_33 761HA		BDT	
<b>TOTAL (hours)</b>				23,5				

  
  
 Saftiadi, Akbar, Rifaldi  
 Personnel In Attendance

\* If Applicable

  
  
 Saftiadi  
 ISP Inspector

  
 Geosha  
 SLB Maintenance Technician

  
 Doni Riyantoro  
 SLB Maintenance Supervisor