

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
4-Apr-24	Manggar Base	16.00 - 22.00	Sleeve Stab JOP16-OSS-025 - Inspection	6	To Be Created		DNM	
OT			Lifting Sub - Lift Sub, >=6"OD, Steel - 5 1/2-FHPB_177 - Inspection		dd_tools:9 April, 2024			
			Lifting Sub - Lift Sub, >=6"OD, Steel - 4 1/2-IFP_RIB11-228 - Inspection		dd_tools:9 April, 2024			
			PD6 CONTROL COLLAR SLEEVE - STABILIZER, UPPER, 9.375 OD, TILED, CRS - 7922 - Ex Machine Shop		WCM_PDORB900_8 April, 2024_SN104107			
			Filter Sub - Downhole Filter Sub, >=6.75"OD, Steel - 675-468 - Inspection		S700M_FS70B0509_02Apr24			
			Filter Sub - Downhole Filter Screen, >=6.75"OD, Steel - Filter Screen 675-468 - Inspection		S700M_FS70B0509_02Apr24			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 12_GP 6924-54 - Inspection		To Be Created			
TOTAL (hours)				6				

* If Applicable

Mangiring, Deny, Sarwo
Personnel In Attendance

Mangiring
ISP Inspector

Amalia Inar
SLB Maintenance Technician

Adi Rahmadita
SLB Maintenance Supervisor