

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
3-Apr-24	Manggar Base	16.00 - 22.00	Float Sub - Float Sub, >=6"OD, Steel - GP-6968-53 - Ex Machine Shop	6	dd_tools:SFS6S_GP-6968-53		DNM	
OT			Splined Mandrel - SPLINED MANDREL, A962 ADJ. BENT HOUSING ASSY - FP96AR0327 - Inspection		SplinedMandrelA962M_03Apr24			
			Splined Mandrel USKW 978849-7 - Inspection		To Be Created			
			C-Link - CLKF6D-BA, DRILL COLLAR ASSY, FULL LTB VER W/ BOX, 6.75 CLINK - 21591 - Inspection		WCM_CLINK675_3 April, 2024_SN N039SAT & 21591			
			Receiver - PD6SRC-AA, 6-3/4" RX COLLAR, MKII S-HOP, POWERDRIVE RSD - N004720 - Inspection		WCM_CLINK675_3 April, 2024_SN N039SAT & 21591			
			Cleaning 1 Set Motor S700M (Bearing Section)					
TOTAL (hours)				6				

* If Applicable

Mangiring, Deny, Sarwo
Personnel In Attendance

Mangiring
ISP Inspector

Inar
SLB Maintenance Technician

Adi Rahmadita
SLB Maintenance Supervisor