

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:   
 Period:   
 Day Rate:   
 Per Diem Rate:

Customer:   
 Contract/ PO Non:   
 Rig / Well:

Date:   
 Our Ref:   
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
23-Dec-23	Manggar Base	08.00 - 22.30	1 Set Motor S700M Stator - STATOR TUBE, 700OD550ID246LG THREADED - 20557 - Inspection	12,5	S700M_23 December, 2023_FS70B0418		DNM	 ERAN A
OT		<i>back</i>	X-Over - M3SB-GC, CROSSOVER SUB, M10, 6-5/ 8 FH BOX X 6-5/8 FH PIN, STAINLESS STEEL - RIB12-482-SBDS - Inspection		To Be Created			
		<i>time</i>	Float Sub - Float Sub, >=8"OD, Steel - RIB12-450-BBS - Ex Machine Shop		To Be Created			
		<i>plus</i>	Lifting Sub - Lift Sub, >=6"OD, Steel 4 1/2"OD Elevator - 4 1/2-IFP ITS 327890 - Ex Machine Shop		To Be Created			
			FMC 06130700F014 - Inspection		To Be Created			
			EXTN SUB, NECKED, PDX9, 8 5/8 REG BU CONN - 103968 - inspection		WCM_Powerdrive_12 December, 2023_EXT SUB and SLEVE			
			PD9 SRX SLEEVE STABILISER - 12-1/8 STABILIZER SLEEVE, SERIES 85, PD9SRX - 65311 - Inspection		WCM_Powerdrive_12 December, 2023_EXT SUB and SLEVE			
			ARC - ARC8D-BB - ARC8D-BB, 8.25 ARC COLLAR ASSEMBLY W/O AIM RECEIVER - 63T21SAT - Inspection		WCM_ARC8D 63T21SAT_23Dec23			
			ADN - ADDC-HA, ASSY, DRILL COLLAR, ADN825 - G8628 - Inspection		WCM_MR ADDC-HA G8628_23Dec23			
<b>TOTAL (hours)</b>				<b>12,5</b>				

\* If Applicable

Mangiring, Riswan, Akbar, Saftiadi  
 Personnel In Attendance

Mangiring  
 ISP Inspector

SLB Maintenance Technician

Dani Rijantoro  
 SLB Maintenance Supervisor