

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (OVERTIME)	BILLING				
				Hours	WO Number	BORG	Segment	Company Representative Signature
12-Feb-24	Manggar Base	17.00 - 22.30	Insepection of : Body Rhino 11625 - 10386103-001 (MPI Inspection), Bore Guide Sleeve 4582488751-2-2 (MPI Inspection), Bore Guide Sleeve 4582488751-2-1 (MPI Inspection), Bore Guide Sleeve 4582415503-4-6 (MPI Inspection), Lower Cap 4582488751-4-3 (MPI Inspection), Lower Cap 4582488751-4-2 (MPI Inspection), Lower Cap 4582488751-4-1 (MPI Inspection), Inner Mandrel - 500798346-4 (DPI Inspection)	5.5	To Be Created		BDT	
TOTAL (hours)				5.5				

Dipo Jeremia Riswan
 Personnel In Attendance

Dipo
 ISP Inspector

* If Applicable

Geosha
 SLB Maintenance Technician

Dani Bayantoro
 SLB Maintenance Supervisor