PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Deny	Customer:	PT. Schlumberger Indonesia	Date :	
Period:	Jul-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
29-Jul-23	Manggar Base	08.00 - 17.00	Top Sub - TOP SUB, 6-5/8 API REG, 5F-6R, A962M - FS96CS1077 - Inspection	8	To Be Created		DNM	
OT			Motor Catcher Sub - TOP SUB, 6-5/8 API REG, 5F-6R, A962M - FS96CS0720 - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=6"OD, Steel - RIB15-002-BBS - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=8"OD, Steel ; 4 1/2IF Pin - RIB15-003-BBS - Inspection		To Be Created			
			Lifting Sub RIB-036 - Inspection		To Be Created			
			TOTAL (hours)	8				

* If Applicable

Mangiring, Deny	Mangiring		
Personnel In Attendance	ISP Inspector	SLB Maintenance Technician	SLB Maintenance Supervisor