

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET




Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
24-Mar-24	Manggar Base	08:00-21:00	Inspected of 1 Set Accelerator Jar 6,5" - 86123H - (MPI Inspection), Reamer - Cutter Block 11625 - 5000222428-1 - (MPI Inspection), Reamer - Cutter Block 11625 - 5000222428-2 - (MPI Inspection),	12	WCD_BDT_24MAR25_ACC50_86123H / WCD_BDT_20MAR24_MISC		BDT	PT. SMITH TOOL INDONESIA
27-Mar-24	Manggar Base	16:00-22:00	Inspected of 1 set Rhino Reamer - 02240 H - (MPI Connection Inspection), Bottom sub - KSU 28-17631-0101 - (MPI Inspection), Bottom sub - KSU 28-17631-0102 - (MPI Inspection)	6	To Be Created		BDT	
28-Mar-24	Manggar Base	16:00-22:00	Inspected 1 set Rhino Reamer - 02240 H - (MPI Connection Inspection After Machine shop), Lower sub AP Jar 6,5 - GHM438 - (MPI Inspection), Kelly Mandrel 6,5" - 10822599-4 - (MPI Inspection)	6	WCD_BDT_30MAR24_MISC		BDT	
31-Mar-24	Manggar Base	08:00-22:00	Inspected of 1 set Rhino Reamer 8000 - 10544689 - (MPI Inspection), Top sub - X67087 / 40719700 - (MPI Inspection), Bottom sub - 10347059-001 - (MPI Inspection), Top sub - R68118 - (MPI Inspection), Bottom sub - R38640 - (MPI Inspection), Bottom sub - K13856 - (MPI Inspection)	13	To Be Created		BDT	
TOTAL (hours)				37				


 Saftiadi, Akbar, Rifaldi
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector


 Geosua
 SLB Maintenance Technician


 Dani Ryaentoro
 SLB Maintenance Supervisor