

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:

Mangiring, Sarwo, Akbar, Riswan, Saftiadi

Customer:

PT DOWELL ANADRILL SCHLUMBERGER

Date:

Period:

Dec-23

Contract/ PO Non:

Our Ref:

Day Rate:

Rig / Well:

Manggar Base

Per Diem Rate :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
16-Dec-23	Manggar Base	08.00 - 12.00	Pony Collar - Drill Collar, >=6.75"OD, Pony, Non-Mag, Straight - SBD-0731 - Ex Machine Shop	8	DD_tools,16 December 2023		DNM	
OT		13.00 - 17.00	PD6 - PDSC6-EA, 6-3/4 LONG SLEEVE-STAB. CU COLLAR - N000267 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			8-1/2" BIAS UNIT BODY, ORBIT 675 - 102638 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			EXTENSION COLLAR, PDX6 - 102894 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			PD6 CONTROL COLLAR SLEEVE - 100398083 - 9000114701-1-5 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			Stator - STATOR TUBE, 700OD550ID246LG THREADED - 10525-STATOR - Inspection		S700M_FS70B0103_14Dec23			
			Lower Rotating Radial Bearing - BEARING, RADIAL, LOWER, INNER, S700M - FS70RB1369 - Inspection		S700M_FS70B0103_14Dec23			
			Bearing Nut - BEARING, RADIAL, LOWER, OUTER, S700M - FS70RB01317 - Inspection		S700M_FS70B0103_14Dec23			
			Upper Stationary Bearing - BEARING, RADIAL, UPPER, OUTER, H700M - FH70RB1145 - Inspection		S700M_FS70B0103_14Dec23			
			Upper Rotating - BEARING, RADIAL, UPPER, INNER, H700M - FH70RB2471 - Inspection		S700M_FS70B0103_14Dec23			
			Driveshaft - S700M, DRIVESHAFT, PIN, 4-1/2 IF - FS70DS0316 - Inspection		S700M_FS70B0103_14Dec23			
			Stator Adapter - HOUSING, STATOR, ADAPTER, FIXED, 7.00 PPK P5, H700M - FH70AU0112 - Inspection		S700M_FS70B0103_14Dec23			
			Motor - DynaForce - 7" - HOUSING, FIXED, STRAIGHT, FLEX - FS70FH1031 - Inspection		S700M_FS70B0103_14Dec23			
			Bearing Housing - HOUSING - BEARING - SLICK - 7.00 S1 - FS70BH0846 - Inspection		S700M_FS70B0103_14Dec23			
			Transmission Shaft - S700M, SHAFT, FLEX, 4330V - FS70TR0185 - Inspection		S700M_FS70B0103_14Dec23			
			Rotor - Rotor Tungsten Carbide GT 7.8 lobe 6.7 stage - 7650W0 - Inspection		S700M_FS70B0103_14Dec23			
				TOTAL (hours)	8			

* If Applicable

Mangiring, Sarwo, Akbar, Riswan, Saftiadi
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

