

**PT. INSPEKTINDO SINERGI PERSADA  
SERVICES TIME SHEET**



Personnel In Attendance:    
 Period:   
 Day Rate:   
 Per Diem Rate:

Customer:   
 Contract/ PO Non:   
 Rig / Well:

Date:   
 Our Ref:

Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
18-Sep-23	Manggar Base	18.00 - 22.00	Bias Unit - 8-1/2" BIAS UNIT BODY, ORBIT 675 - 102527 - Inspection	4	WCM_18 September, 2023_PDORB675_97761		DNM	
		OT <input checked="" type="checkbox"/>	ADN - AZIMUTHAL DENSITY DRILL COLLAR (HIGH STRENGTH), SLICK, 6-3/4 ADN - 2533 - Inspection		To Be Created			
			ADN - AZIMUTHAL DENSITY DRILL COLLAR (HIGH STRENGTH), SLICK, 6-3/4 ADN - G2263 - Inspection		To Be Created			
			Clamp-On Stabilizer - ADCS-CB, ASSY STABILIZER 8-1/4" OD, 6-3/4" ADN, LASER HARDFACED - OSS23-00543 - Inspection		To Be Created			
			Pony Collar - Drill Collar, >=6.75"OD, Pony, Non-Mag, Straight - 21559J - Inspection		To Be Created			
<b>TOTAL (hours)</b>				4				<i>EVANA</i>

\* If Applicable

Mangiring, Sarwo, Deny  
Personnel In Attendance

Mangiring  
ISP Inspector

\_\_\_\_\_  
SLB Maintenance Technician

Doni Bayuanto  
SLB Maintenance Supervisor