

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangiring, Deny, Sarwo, Jeremia, Rifaldi, Dipo
 Period: Dec-23
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non: _____
 Rig / Well: Manggar Base

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
21-Dec-23	Manggar Base	18.00 - 22.00	MSSB - MSSB-JC, CROSSOVER SUB, NO LWD DH (8.25 M10), STAINLESS STEEL - OVP31381 - Inspection	4	To Be Created		DNM	 Doni Rijantoro SLB Maintenance Supervisor
OT			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0002275-5-4 - Ex Machine Shop		To Be Created			
			MSSB - MSSB-GC, CROSSOVER SUB, M10, 6-5/8 FH BOX X 6-5/8 FH PIN, STAINLESS STEEL - 01P0001936-1-4 - Ex Machine Shop		To Be Created			
			Gyro Collar - 825 Gyrodata Collar - 01P0002275-10-5 - Ex Machine Shop		To Be Created			
			MSSB - MSSB-KC, CROSSOVER SUB, M10, 6-5/8 FH PIN X 6-5/8 FH PIN, STAINLESS STEEL - 01P0001936-2-4 - Ex Machine Shop		To Be Created			
			Float Sub - Float Sub, >=8"OD, Steel - RIE14-011-BBS - Inspection		DD_tools;20 December, 2023			
			UBHO RIB12-248-BBS - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=8"OD, Steel - 6 5/8-FHP_171 - Inspection		DD_tools;20 December, 2023			
			Lifting Sub 5184B - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=8"OD, Steel - 6 5/8-FHB_RIB12-449 - Inspection		To Be Created			
			MMA - ASSY, MMA M10 MODULATOR JUMPER, 5.1 ID COLLAR, INCCNEL - SN54 - Inspection		MWD-20122023-Ilx Yani			
			MTA - ASSEMBLY, 5.9" MTA JUMPER - 91193486 - Inspection		MWD-20122023-Ilx Yani			
			MMA - ASSY, 5.1 MTA JUMPER - 310420-16 - Inspection		MWD-20122023-Ilx Yani			
			MMA - ASSEMBLY, 5.9" MMA JUMPER - SN28 - Inspection		MWD-20122023-Ilx Yani			
			String Stab NN - Inspection		To Be Created			
TOTAL (hours)				4				

* If Applicable

Mangiring, Deny, Sarwo, Jeremia, Rifaldi, Dipo
 Personnel In Attendance

Mangiring
 ISF Inspector

 SLB Maintenance Technician

Doni Rijantoro
 SLB Maintenance Supervisor