

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:

Mangiring, Sarwo, Akbar, Riswan, Saftiadi

Period:

Dec-23

Day Rate:

Per Diem Rate :

Customer:

PT DOWELL ANADRILL SCHLUMBERGER

Contract/ PO Non:

Rig / Well:

Manggar Base

Date :

Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
16-Dec-23	Manggar Base	08.00 - 12.00	Pony Collar - Drill Collar, >=6.75"OD, Pony, Non-Mag, Straight - SBD-0731 - Ex Machine Shop	8	DD_tools,16 December 2023		DNM	
OT		13.00 - 17.00	PD6 - PDSC6-EA, 6-3/4 LONG SLEEVE-STAB. CU COLLAR - N000267 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			8-1/2" BIAS UNIT BODY, ORBIT 675 - 102638 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			EXTENSION COLLAR, PDX6 - 102894 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			PD6 CONTROL COLLAR SLEEVE - 100398083 - 9000114701-1-5 - Inspection		WCD_PDORB675_18DEC2023_SN97105			
			Stator - STATOR TUBE, 700OD550ID246LG THREADED - 10525-STATOR - Inspection		S700M_FS70B0103_14Dec23			
			Lower Rotating Radial Bearing - BEARING, RADIAL, LOWER, INNER, S700M - FS70RB1369 - Inspection		S700M_FS70B0103_14Dec23			
			Bearing Nut - BEARING, RADIAL, LOWER, OUTER, S700M - FS70RB01317 - Inspection		S700M_FS70B0103_14Dec23			
			Upper Stationary Bearing - BEARING, RADIAL, UPPER, OUTER, H700M - FH70RB1145 - Inspection		S700M_FS70B0103_14Dec23			
			Upper Rotating - BEARING, RADIAL, UPPER, INNER, H700M - FH70RB2471 - Inspection		S700M_FS70B0103_14Dec23			
			Driveshaft - S700M, DRIVESHAFT, PIN, 4-1/2 IF - FS70DS0316 - Inspection		S700M_FS70B0103_14Dec23			
			Stator Adapter - HOUSING, STATOR, ADAPTER, FIXED, 7.00 PPK PS, H700M - FH70AU0112 - Inspection		S700M_FS70B0103_14Dec23			
			Motor - DynaForce - 7" - HOUSING, FIXED, STRAIGHT, FLEX - FS70FH1031 - Inspection		S700M_FS70B0103_14Dec23			
			Bearing Housing - HOUSING - BEARING - SLICK - 7.00 S1 - FS70BH0846 - Inspection		S700M_FS70B0103_14Dec23			
			Transmission Shaft - S700M, SHAFT, FLEX, 4330V - FS70TR0186 - Inspection		S700M_FS70B0103_14Dec23			
			Rotor - Rotor Tungsten Carbide GT 7:8 lobe 6.7 stage - 7650WO - Inspection		S700M_FS70B0103_14Dec23			
TOTAL (hours)				8				

* If Applicable

Mangiring, Sarwo, Akbar, Riswan, Saftiadi
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
16-Dec-23	Manggar Base	17:00-22:00	Inspect of Top Sub DTU 22.000 - M01460 - (MPI Inspection), Bottom Sub DTU 22.000 - 99367 H - (MPI Inspection), 2 Ea ARM XTU 22.000 - G08539 - (MPI Inspection)	5	WCD_BDT_21DEC23_MISC		BDT	PT. SMITH TOOL INDONESIA
TOTAL (hours)				5				



 Saftiadi Akbar, Sarwo
 Personnel In Attendance

* If Applicable



 Saftiadi
 ISF Inspector


 Geosh
 SLB Maintenance Technician


 Doni Riyanto
 SLB Maintenance Supervisor