






**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**

Personnel In Attendance: Hajili, Herwanto, Aziz Customer: PT. Schlumberger Indonesia Date: 18-Oct-23  
 Period: Sept 21 - Oct 20 2023 Contract/ PO Non: - Our Ref: -  
 Day Rate: - Rig / Well: CIB Form No.: -  
 Per Diem Rate: -

Billing Date	Rig / Loc*	Time*	ACTIVITY (TOOL_NAME_SIN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: Telescope Collar_G3759_E Machine Shop	Hours	WO Number	BORG	Segment	Company Representative Signature
17-Oct-23	CIB	17:30 - 22:30	Lifting sub - 658R006 (Inspected)					
			Stator Adapter - STATOR ADAPTER, W/SR A962 ADJ, BENT HOUSING - FP95AU0223 (Inspected)					
			Bias Unit Ext Sub - EXTN SUB, NECKED, PDX9/PDX1, 8 5/8 REG BU CONN - 98968 (Inspected)					
			Continue 1 Set Mud Motor 962 (Steam and Drying)					
			SRX - PD8SRX-AA, 8 1/4" MK2 S-HOP RECEIVER SUB - 70185 (Cleaning)					
			Control Collar (threaded) - PDSC9-BI, COLLAR ASSEMBLY, PD900 - N19M0086 (Cleaning)					
			PD Control Collar - PD25CC-AB, COLLAR ASSEMBLY, 6-5/8 X NC-61 - 65239 (Cleaning)					
			PD9 CONTROL COLLAR SLEEVE - CONTROL COLLAR SLEEVE, SUICK, HARDFACED, PD900 - OSS 060871B (Cleaning)					
			Bias Unit - BIAS UNIT/COLLAR ASSY, 12 1/4 PDX, 8 5/8 REG SUB CONNECTION, - 83894 (Cleaning)					
			Bias Unit - BIAS UNIT/COLLAR ASSY, 825, - 55186 (Cleaning)					
			Bias Unit Ext Sub - EXTN SUB, NECKED, PDX9/PDX1, 8 5/8 REG BU CONN - 100044 (Cleaning)					
			Bias Unit Ext Sub - EXTN SUB, NECKED, PDX8/PDX1- 96137 (Cleaning)					
<b>TOTAL (hours)</b>								

  
 Herwanto  
 ISP Personnel In Attendance

  
 Hajili  
 ISP Inspector

  
 SLB Maintenance Technician

  
 SLB Maintenance Supervisor