PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Sarwo, Riswan, Jeremia, Akbar, Rifaldi	Customer:	PT DOWELL ANADRILL SCHLUMBERGER	Date :	
Period:	Jan-24	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
18-Jan-24	Manggar Base	17.00 - 23.00	1 Set Motor S700M Stator - STATOR TUBE, 700OD550ID246LG THREADED - 12926 - Inspection	6	S700M_FS70B0509_16Jan24		DNM	
OT			Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 71131 - Inspection		To Be Created			
			Blank Sleeve NN - Inspection		To Be Created			
			ADN Pony - AZIMUTHAL DENSITY NON-MAGNETIC SUB, 6-3/4 - KSBD 15221 - Inspection		WCM-170124-H7427/2 ADN6			
			Float Sub - Float Sub, >=4.75"OD, Steel - JOP10-BTS-099 - Inspection		To Be Created			
			NMDC - Drill Collar, >=6"OD, Non-Mag, Straight - 752577-1 - Ex Machine Shop		To Be Created			
			NMDC - Drill Collar, >=6.75"OD, Non-Mag, Straight - AWS 675-30-7900 - Ex Machine Shop		To Be Created			
			Sleeve Stab NN - Inspection		To Be Created			
			Filter Sub - Downhole Filter Screen, >=6.75"OD, Steel - Filter Screen 675-468 - Inspection		FilterSub675_15Jan24			
			Float Sub - Float Sub, >=6"OD, Steel - GP-7035-39 - Inspection		To Be Created			
			Lifting - Lift Sub, >=4"OD, Steel - 3 1/2-IFB_RIB12-512 - Inspection		To Be Created			
			Lifting Sub 201 - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=4"OD, Steel - NC35P_RIB12-336 - Inspection		To Be Created			
			TOTAL (hours)	6				

* If Applicable

Mangiring, Sarwo, Riswan, Jeremia, Akbar, Rifaldi	Mangiring		
Personnel In Attendance	ISP Inspector	SLB Maintenance Technician	SLB Maintenance Supervisor

Digitally signed by Adi Rahmadita
DN: CN=Adi Rahmadita, E=arahmadita@slb.com
Location: slb Manggar Base
Date: 2024.01.21 14:02:55 +08'00'