# PT. INSPEKTINDO SINERGI PERSADA

## SERVICES TIME SHEET

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | Hajili, Egi, Jaelani | Customer: | PT.Schlumberger Indonesia | Date : | 13-Sep-23 |
| Period: | Aug 21 - Sept 20, 2023 | Contract/ PO Non: | - | Our Ref: | - |
| Day Rate: | - | Rig / Well: | CIB | | |
| Per Diem Rate : | - | | | Form No. : | |

| Billing Date | Rig / Loc* | Time* | ACTIVITY (TOOL NAME_SN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_E Machine Shop | BILLING | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | Hour/s | WO Number | BORG | Segment | Company Representative Signature |
| 8-Sep-23 | CIB | 17.30 - 21.00 | MUD MOTOR SLEEVE - STABILIZER,17 1/4 GD,5 STRAIGHT BLADES,8.6" LG C - OSS1006158B_HF6K (Inpsected) | | | | D&M | |
| | | | Power Drive - STEERING SLEEVE CLAMP, RVSU675 - 4581548110-1-0008 (Inspected) | | | | | |
| | | | Archer - OUTER STRIKE RING, RVSU675 - H78577 (Inspected) | | | | | |
| | | | Archer - STR-SLEEVE ASSY, FOR 8-1/2 IN HOLE, TC-TILES, RVSU675 - 202929-1-1 (Inpsected) | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | TOTAL (hours) | | | | | |

Herwanto
ISP Personnel In Attendance

Hajili
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

Dipindai dengan CamScanner