PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Deny, Riswan, Tomanro	Customer:	PT DOWELL ANADRILL SCHLUMBERGER	Date :	
Period:	Jun-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
2-Jun-24	Manggar Base	08.00 - 22.00	PDBU Body ORB675 - 103924 - Inspection	13	MT-WCD_PDORB675-100827_240601		DNM	
OT			PDSRC Pressure Housing - SHORT-HOP RECEIVER CARTRIDGE, POWERDRIVE RSD - 42638 - Inspection		To Be Created			
			Sleeve Stabilizer - THREAD PROTECTOR, PD675 RSD COLLAR, HARDFACED - JOP21-OSS-001 - Inspection		MT-WCD_PDOR675_SN104940_240602			
			Lifting Sub - 5 1/2 FH Box Lift Sub, >=6"OD, Steel - 5 1/2FHB_RIB22-HMH-005 - Inspection		To Be Created			
			PD6 - PDSC6-BA, 6-3/4 LONG SLEEVE-STAB. CU COLLAR - N003569 - Inspection		MT-WCD_PDORB675-100827_240601			
			Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 60474 - Inspection		MT-WCD_PDORB675-100827_240601			
			Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - N19M0576 - Inspection		To Be Created			
			NMDC - Drill Collar, >=8"OD, Non-Mag, Straight - 80-30-10394 - Inspection		dd_tools;31 May, 2024			
			PD6 CONTROL COLLAR SLEEVE - 100398083 - 9000114701-1-5 - Inspection		MT-WCD_PDORB675-100827_240601			
			PDSRC Pressure Housing - SHORT-HOP RECEIVER CARTRIDGE, POWERDRIVE RSD - 42803 - Inspection		MT-WCD_PDORB675-100827_240601			
			Fload Valve RIB 11 - Inspection		To Be Created			
			Bias Unit Ext Sub - EXTENDED EXTENSION SUB, PDX6 - JOP19-OSS-007 - Inspection		MT-WCD_PDORB675-100827_240601			
			UBHO - UBHO6 ,connection : NCO 50 Pin x NC50Box - RIB24-BBS-265 - Ex Machine Shop		dd_tools;3 June, 2024			
			TOTAL (hours)	13				

* If Applicable

Mangiring, Deny, Riswan, Tomanro	Mangiring	18 June 2024	18 JUN '24
Personnel In Attendance	ISP Inspector	SLB Maintenance Technician	ON BEHALF : RIDWAN S. SLB Maintenance Supervisor