

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: Mangiring, Sarwo, Deny, Rifaldi, Jeremia, Akbar  
 Period: Sep-23  
 Day Rate:                       
 Per Diem Rate:                     

Customer: PT DOWELL ANADRILL SCHLUMBERGER  
 Contract/ PO Non:                       
 Rig / Well: Manggar Base

Date:                       
 Our Ref:                     

Form No. :                     

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
30-Sep-23	Manggar Base	08.00 - 21.30	1 Set Motor700 Bearing Section Stator - STATOR TUBE, 700OD550ID246LG THREADED - F70S0278 - Inspection ✓	11,5	A700M_06941_29Sep23		DNM	 Eban A
OT ✓		<i>break</i>	String Stabilizer - Stabilizer, >=6.75" OD Body, String, Steel, Integral Spiral Blade - 8 1/8_GP-7034-41 - Inspection		To Be Created			
		<i>time</i>	NB Stabilizer - Stabilizer, >=6.75" OD Body, Near Bit, Steel, Integral Spiral Blade - 8 3/8_GP 7034-53 - Inspection		To Be Created			
		<i>2hrs</i>	String Stabilizer - Stabilizer, >=6.75" OD Body, String, Steel, Integral Spiral Blade - 9 3/8_R3296-H - Inspection		DD_tools;2Oct2023			
			Sonic Collar - SD6D-BA, ASSY COLLAR 6SONIC, GROOVELESS - 43045 - Inspection		WCM_SD6D-BA 43045_30Sep23			
			Sleeve Stab JOP22-OSS-001 - Inspection		To Be Created			
			Control Collar - PDSC6-GA , 6-3/4" SLEEVE-STAB. CU COLLAR, SLENDER ANCHOR BOLT HOLE - N9M1084 - Inspection		WCD_30SEP2023_PDORB675_SN97105			
			Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 60460 - Inspection		WCD_30SEP2023_PDSRX6_SN60460			
			8-1/2" BIAS UNIT BODY, ORBIT 675 - 102638 - Inspection		WCD_30SEP2023_PDORB675_SN97105			
			MSSA - MSSA-EC, CROSSOVER SUB, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - 01P0002900-8-1 - Inspection		To Be Created			
			Lifting Sub - Lift Sub, >=6"OD, Steel Elevator 4 1/2"OD - 5 1/2FHB_195 - Inspection		To Be Created			
			MSSA - MSSA-BQ, CROSSOVER SUB, M10, 5-1/2 FH BOX X 5-1/2 FH PIN, STAINLESS STEEL - 01P0002900-26-2 - Inspection		To Be Created			
			EXTENSION COLLAR, PDX6 - 102894 - Inspection		WCD_30SEP2023_PDORB675_SN97105			
			MTK - ASSY, MMA M10 TURBINE JUMPER, 5.1" ID COLLAR, INCONEL - SN482 - Inspection		MWD-29092023-Backload			
			MMA - ASSY, 5.1 MTA JUMPER - 310420-16 - Inspection		MWD-29092023-Backload			
			Gyro Collar - 675 Gyrodata Collar - 01P0002847-4-1 - Inspection		To Be Created			
<b>TOTAL (hours)</b>				<b>11,5</b>				

\* If Applicable

Mangiring, Sarwo, Deny, Rifaldi, Jeremia, Akbar  
 Personnel In Attendance

Mangiring  
 ISP Inspector

SLB Maintenance Technician

Doni Riyantoro  
 SLB Maintenance Supervisor