PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET

	NADRILL SCHLUMBERGER Date				
Period: Nov-23 Contract/ PO Non:	Our l	Ref:			
Day Rate: Rig / Well: Manggar Base					
Per Diem Rate :	Form	1 No. :			
		BILLING			
Billing Date Rig / Loc* Time*	ACTIVITY He	our/s WO Number	BORG BORG	Segment	Company Representative Signature
5-Nov-23 Manggar Base 13.00 - 22.00 Pony Collar - Drill Collar, >=8"OD, Pony, Non-Mag, Straight - 21688-J - In	Pony Collar - Drill Collar, >=8"OD, Pony, Non-Mag, Straight - 21688-J - Inspection		ed		
OT Skewle Lifting Sub GP7127-109 - Inspection		To Be Creat	ed ·		
Lifting Sub 311 - Inspection		To Be Creat	ed		
Lifting Sub - Lift Sub, >=8"OD, Steel - 6 5/8-RPP_BBS 5184B - Inspection		To Be Creat	ed '		
PD6 CONTROL COLLAR SLEEVE - 100398083 - JOP22-OSS-003 - Insp	ection	To Be Creat	ed -		
Blank Sleeve NN - Inspection		To Be Creat	ed .		
Control Collar - PDSC6-GA , 6-3/4" SLEEVE-STAB. CU COLLAR, SLENDER AND	Control Collar - PDSC6-GA , 6-3/4" SLEEVE-STAB. CU COLLAR, SLENDER ANCHOR BOLT HOLE - N9M1084 - Inspection		ed	an and a second	
Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 71	Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 71131 - Inspection		ed	DNM	
Bias Unit - 8-1/2"" BIAS UNIT BODY, ORBIT 675 - 102527 - Inspection		To Be Creat	ed	J. DAM	
PDSRC Pressure Housing - RECEIVER CARTRIDGE MKII SHORTHOP -	PDSRC Pressure Housing - RECEIVER CARTRIDGE MKII SHORTHOP - 70814 - Inspection		ed		
Bias Unit Ext Sub - EXTENDED EXTENSION SUB, PDX6 - 99340 - Inspection	Bias Unit Ext Sub - EXTENDED EXTENSION SUB, PDX6 - 99340 - Inspection		ed		
Jum Nut S-400605 - Inspection	Jum Nut S-400605 - Inspection		ed	*	
				-	
			*		
					0
			j.*:	9	1
	TOTAL (hours)	8			EIAN

Mangiring, Sarwo, Akbar, Riswan
Personnel In Attendance

Mangiring ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor