

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Mangiring, Sarwo, Deny, Dipo, Jeremia, Rifaldi
 Period: Oct-23
 Day Rate:
 Per Diem Rate:

Customer: PT DOWELL ANADRILL SCHLUMBERGER
 Contract/ PO Non:
 Rig / Well: Manggar Base

Date:
 Our Ref:

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
18-Oct-23	Manggar Base	18.00 - 22.00	Torquer - UPPER TORQUER ASSEMBLY TC BEARING 5N-M COIL - 22-3374 - Inspection	4	PD_ET_20231018_01		DNM	
OT ✓			Torquer - PDLTG-AC PD ORBIT LOWER TORQUER ASSEMBLY - 18-990 - Inspection		PD_ET_20231018_01			
			Torquer - LOWER TORQUER ASSEMBLY TWO PIECE TC BEARING - 22-3472 - Inspection		PD_ET_20231018_01			
			Torquer - UPPER TORQUER ASSEMBLY TC BEARING 5N-M COIL - 18-282 - Inspection		PD_ET_20231018_01			
			Antenna - ANTENNA ASSEMBLYSHORTHOP - SEC 5824 - Inspection		PD_ET_20231018_01			
			Antenna - ANTENNA ASSEMBLYSHORTHOP - SEC 5936 - Inspection		PD_ET_20231018_01			
			Control Collar (threaded) - CONTROL COLLAR 6-3/4", WITH SLEEVE STABILIZER OPTION, PD-ARCHER - N9M1154 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			Receiver - 6-3/4 MK2 S-HOP RECEIVER SUB, POWERDRIVE RSD - 60460 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			PD6 CONTROL COLLAR SLEEVE - STABILIZER, UPPER, 8.375 OD, WC TILED, CRS - 31929 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			SHORT-HOP RECEIVER CARTRIDGE, PD475 RSD - SN70864 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			Bias Unit Ext Sub - EXTENSION COLLAR, PDX5 - 98832 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			8-1/2" BIAS UNIT BODY, ORBIT 675 - 103315 - Inspection		WCM_19 October, 2023_PDORB675_94701			
			Telescope Collar - MDCIX-AB, 6-3/4 IWOB, ASSY W/INT. ALIGN. KEY, BOX x BOX, NO R.O.P. - N001294 - Ut Sharewave		MWD-181023-N001294_UT			
TOTAL (hours)				4 ✓				

* If Applicable

Mangiring, Sarwo, Deny, Dipo, Jeremia, Rifaldi
 Personnel In Attendance

Mangiring
 ISP Inspector

 SLB Maintenance Technician

Doni Rijantoro
 SLB Maintenance Supervisor