

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
15-Mar-24	Manggar Base	16.00 - 24.00	UBHO - Orientating Sub, >=6.75"OD, Steel - RIB10-063-BBS - Inspection	8			DNM	
OT			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 23139-0103 - Inspection					
			X-Over - MSSA-EC-NG, CROSSOVER, 5-1/2 FH PIN X 5-1/2 FH PIN, NON MAG SST - JOP22-BTS-005 - Inspection					
			ADN Pony - AZIMUTHAL DENSITY NON-MAGNETIC SUB, 6-3/4 - KSBD 15221 - Inspection					
			Telescope Collar - 6.75 M10 COLLAR, INTERNAL ALIGNMENT KEY, BOX x BOX, NO R.O.P., P-550 MATL - G3371 - Inspection					
			MSSA-DC - MSSA-DC, CROSSOVER, NC50 PIN X 5-1/2 FH PIN, SST - 754690 7-8 - Inspection					
			ARC - T1004302, DRILL COLLAR ASSY, 6.75 ARC W/O AIM RECEIVER - H8188SAT - Inspection					
			ADN Collar - ADDC-CE, AZIMUTHAL DENSITY DRILL COLLAR W/8.25 LASER HARD FACED INTGR SZR, 6-3/4" ADN - H7427/2 - Inspection					
TOTAL (hours)				8				

* If Applicable

Mangiring, Sarwo, Deny, Christoper
 Personnel In Attendance

Mangiring
 ISP Inspector

18/03/24
 SLB Maintenance Technician

Doai Riyantoso
 SLB Maintenance Supervisor