# PT. INSPEKTINDO SINERGI PERSADA

## SERVICES TIME SHEET

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | Hajili, Herwanto, Aziz | Customer: | PT.Schlumberger Indonesia | Date : | 12-Oct-23 |
| Period: | Sept 21 - Oct 20, 2023 | Contract/ PO Non: | - | Our Ref: | - |
| Day Rate: | - | Rig / Well: | CIB | | |
| Per Diem Rate : | - | | | Form No. : | |

| Billing Date | Rig / Loc* | Time* | ACTIVITY (TOOL NAME_SN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_E Machine Shop | BILLING | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | Hour/s | WO Number | BORG | Segment | Company Representative Signature |
| 11-Oct-23 | CIB | 17.30 - 23.00 | 1 Set Mud Motor 675 for MEDCO MEPN (Cleaning) | | | | D&M | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | TOTAL (hours) | | | | | |

Herwanto Aziz
ISP Personnel In Attendance

Hajili
ISP Inspector

SLB Maintenance Technician

12/10/23
SLB Maintenance Supervisor

Dipindai dengan CamScanner