

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
17-May-24 ✓	Manggar Base	17:00-22:00	Inspected of Reamer Bottom sub 8000 - KSBD 15233 - (MPI Inspection), Reamer Top sub 8000 - 0693951 / 73931H - (MPI Inspection), Reamer Cutter Block 8000- 5000207421-1- (MPI Inspection)	5 ✓	To Be Created		BDT	PT. SMITH TOOL INDONESIA
20-May-24 ✓	Manggar Base	17:00-22:30	Inspected of 1 set ACCELERATOR 6,5" SL1 - 11328 J - (MPI Inspection and Boroscope) & 1 Set AP JAR 6,5" SL-1 - 40472J - (MPI Inspection and Boroscope)	5,5	To Be Created		BDT	
TOTAL (hours)				10,5				

Saftiadi, Akbar, Riswan
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

SLB Maintenance Supervisor