PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Sarwo, Saftiadi, Rifaldi, Jeremia, Riswan	Customer:	PT DOWELL ANADRILL SCHLUMBERGER	Date :	
Period:	Oct-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
7-Oct-23	Manggar Base	08.00 - 20.00	Lifting Sub - Lift Sub, >=8"OD, Steel - 6 5/8-FHP_RIB12-448 - Inspection	10	DD_tools; 5 oct 2023		DNM	
OT		break	Lifting Sub - Lift Sub, >=8"OD, Steel - 6 5/8-RP_167 - Inspection		DD_tools; 5 oct 2023			
		time	Ecoscope Collar - DV6M DRILL COLLAR - 1705A - Inspection		To Be Created			
		2hrs	Ecoscope Collar - DV6M DRILL COLLAR - 1829 - Inspection		To Be Created			
			Telescope Collar - MDCIX-BA, 6-3/4 NON-IWOB COLLAR, INT. ALIGN. KEY, BOX x BOX, NO R.O.P., P-550 - N000814 - Inspection		MWD-071023-N000814			
			MSSA - CROSSOVER, M10, 5-1/2 FH PIN X 5-1/2 FH PIN, STAINLESS STEEL - BKS 23139-0103 - Inspection		MWD-071023-N000814			
			MSSA - MSSA-CC, CROSSOVER SUB, 6.5 CDR UH/NO LWD UH (6.75 M10), STAINLESS STEEL - RIB12-479-SBDS - Inspection		MWD-071023-N000814			
			1 Set Motor A962M Stator 962 - STATOR TUBE, 962OD785ID228LG, THREADED - 10620B1D2D3 - Inspection		A962M_FP96AL0346_07Oct23			
			TOTAL (hours)	10				

* If Applicable

Mangiring, Sarwo, Saftiadi, Rifaldi, Jeremia, Riswan
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

Doni Prijantoro
SLB Maintenance Supervisor