# PT. INSPEKTINDO SINERGI PERSADA
## SERVICES TIME SHEET

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | EDIK, YANUAR, HERWANTO | Customer: | PT.Schlumberger Indonesia | Date : | 27/10/2023 |
| Period: | Oct 21 - Nov 20, 2023 | Contract/ PO Non: | - | Our Ref: | - |
| Day Rate: | - | Rig / Well: | CIB | | |
| Per Diem Rate : | - | | | Form No. : | |

| Billing Date | Rig / Loc* | Time* | ACTIVITY (TOOL NAME_SN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) | BILLING | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | Hour/s | WO Number | BORG | Segment | Company Representative Signature |
| 27/10/2023 | CIB | 17.30 - 23.00 | **MLWD TOOLS** | - | - | - | D&M | |
| | | | 2 EA CROSSOVER SUB SN.BKS 22921-03, N00746 - INSPECTION | | | | | |
| | | | GAP SUB 8" SN.SN97 - INSPECTION | | | | | |
| | | | 2 EA ARC8 COLLAR SN.ZZ223741,C0012SAT - INSPECTION | | | | | |
| | | | 2 EA DDR6 COLLAR SN.G5268, V0759/1 - INSPECTION | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | TOTAL (hours) | | | | | |

YANUAR & HERWANTO
ISP Personnel In Attendance

EDIK SUHAYA
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor