

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
15-Jan-24	Manggar Base	17.00 - 22.00	Telescope Collar - 8.25 M10 HF NON-IWOB COLLAR, INT. ALIGN. KEY, BOX X BOX, NO R.O.P. - SN14 - Inspection	5	WCM-150124-SN14		DNM	
OT			MSSB - MSSB-KC, CROSSOVER, 6-5/8 FH PIN X 6-5/8 FH PIN, SST - BKS 19715-0302 - Inspection		WCM-150124-SN14			
			X-Over - MSSB-IC, CROSSOVER SUB, NO LWD UH (8.25 M10), STAINLESS STEEL - OVP33802 - Inspection		WCM-150124-SN14			
			Pony Collar - Drill Collar, >=6.75"OD, Non-Mag, Straight - RIB11-180-SBDS - Inspection		dd_tools:13 January, 2024			
			Pony Collar - Drill Collar, >=4.75"OD, Pony, Non-Mag, Straight - SBD-0575 - Inspection		To Be Created			
			NMDC - Drill Collar, >=4.75"OD, Non-Mag, Straight - SBD-0737 - Inspection		dd_tools:12 January, 2024			
			NMDC - Drill Collar, >=8"OD, Non-Mag, Straight - 6951 - Inspection		dd_tools:12 January, 2024			
				TOTAL (hours)	5			

* If Applicable

Mangiring, Sarwo, Saftiadi, Akbar, Riswan
 Personnel In Attendance

Mangiring
 ISP Inspector

SLB Maintenance Technician

Adi Rahmasta
 SLB Maintenance Supervisor