# PT. INSPEKTINDO SINERGI PERSADA
## SERVICES TIME SHEET

| | | | | | |
|---|---|---|---|---|---|
| Personnel In Attendance: | Hajili | Customer: | WELL SERVICE CEMENTING | Date : | 2-Nov-23 |
| Period: | 21 Oct Thru 20 Nov 2023 | Contract/ PO No: | 2023102401 | Our Ref: | |
| Day Rate: | | Rig / Well: | SLB CIB | | |
| Per Diem Rate : | | | | | |

| No | Day & Date | Rig / Loc* | Time* | ACTIVITY | BILLING | | |
|---|---|---|---|---|---|---|---|
| | | | | | Day | Mob/ Demob (USD) | Per diem (Day) |
| 1 | 27-Oct-23 | CIB | 08.30 - 19.30 | Full Body Inspection 6 1/8 Storm Valve and 9 5/8 DLT Packer For Medco Grissik | 1 | | |
| 2 | 28-Oct-23 | CIB | 08.30 - 21.30 | Full Body Inspection 3 1/2 Unloader, 4 1/2 Unloader and 4 3/4 Storm Valve For Medco Grissik | 1 | | |
| 3 | 30-Oct-23 | CIB | 08.30 - 17.30 | Re-Bevel and Refacing Bottom Sub 4 1/2 Unloader for Medco Grissik | 1 | | |
| 4 | 1-Nov-23 | CIB | 08.30 - 12.00 | Full Body Inspection Bottom Sub 3 1/2 Unloader for Medco Grissik. | 1 | | |
| 5 | 2-Nov-23 | CIB | 13.00 - 14.00 | Dimensional and Visual Thread Inspection Bottom Sub 4 3/4 Strom Valve for Medco Grissik. | 1 | | |
| | | | | **TOTAL (Days)** | **5** | | |
| | | | | **TOTAL (USD)** | | | |
| | | | | **GRAND TOTAL** | | | |

* If Applicable

| Consumable Material Usage | | | | |
|---|---|---|---|---|
| No | Date & Day | Material Usage | Quantity | Remark |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

PT. INSPEKTINDO SINERGI PERSADA

HAJILI
Personnel In Attendance

Contractor Representative

Rig Representative

Agus R
The Company Representative