

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
1-Jun-24	Manggar Base	08.00 - 22.30	1 Set Motor A962M Stator 962 - STATOR TUBE, 962OD785ID228LG, THREADED - 19755W0D1 - Inspection	13,5	A962M_FP96BH1144_31May24		DNM	
OT			Jar 474-65888 - Inspection		To Be Created			
			ARC - T1004302,DRILL COLLAR ASSY, 6.75 ARC W/O AIM RECEIVER - V8875SAT - Inspection		WCM_010624_01			
			Rotor Coupling - SOCKET, TOP, HT-2, 3-1/2 SLIMLINE H-90, S700M - FS67CU5212 - Inspection		S700M_31May2024_ShaftCoupling&NewPart			
			Transmission Shaft - S700M, TIE ROD, BOOTED, HT-2 - FS67TR4370 - Inspection		S700M_31May2024_ShaftCoupling&NewPart			
			ARC - ARC8D-BB - ARC8D-BB, 8.25 ARC COLLAR ASSEMBLY W/O AIM RECEIVER - ZA91J5T1 - Inspection		WCM_300524_01			
			MSSB - MSSB-MC, CROSSOVER, 5-1/2 IF PIN X 6-5/8 FH PIN, SST - 7397-01 - Inspection		WCM_300524_01			
				TOTAL (hours)	13,5			

* If Applicable

Mangiring, Sarwo, tomanro, Deny
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

18 June 2024

ON BEHALF : RIMAN S.

SLB Maintenance Supervisor