

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Saftiadi, Akbar, Rifaldi
 Period: May - June 2024
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. SMITH TOOL INDONESIA
 Contract/ PO Non: _____
 Rig / Well: Manggar Base

Date: _____
 Our Ref: _____

Form No. : _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
26-May-24	Manggar Base	08:00-22:00	Inspected of Hydra Jar - JAR - 4-3/4 OD -- 42847J - (MPI Inspection and Boroscope)	13	To Be Created		BDT	PT. SMITH TOOL INDONESIA
			Inspected of Reamer - (RHINO XS BODY 10000 W/HVOF) - 10069812-001 - 10288664-001 - (MPI Inspection), Reamer - (RHINO REAMER XS Spring Retainer 10000) - 9169102-001 - (MPI Inspection), Reamer - (RHINO REAMER XS PISTON 10000) - AJ06429 - (MPI Inspection), Reamer - (RHINO REAMER XS Inner Mandrel 10000) - 9479912-003 - (MPI Inspection), Reamer - (RHINO REAMER XS DRIVE RING 10000) - 9994002-001 - (MPI Inspection) Reamer - (RHINO REAMER STOP RING 10000) 9479910-005, - (MPI Inspection) Reamer - Upper CAP, 10000-10375 RHINO XS2 - 9158319-004 - (MPI Inspection), Reamer - Cutter Block 10000 - 5000244784-1 - (MPI Inspection)		To Be Created		BDT	
			Inspected of Under Reamer - RHINO XS, UNDERREAMER - 8000 - 9291626-001 - S93655A (MPI Inspection), Reamer Cutter Block 8000 - 10954104-3 - (MPI Inspection), Reamer Cutter Block 8000 - 5000252999-2 - (MPI Inspection)		WCD_BDT_02JUN24_RR8000_9291626-001		BDT	
4-Jun-24	Manggar Base	17:00-22:00	Inspected of Jar - HQ650 Upper Flex Joint - OSCA335712 - (MPI Inspection), Jar - HQ650, PRESSURE CYLINDER - OSCA294218 - (MPI Inspection), Jar - HQ650, CONNECTOR SUB - Y85535 - (MPI Inspection), (MPI Inspection), Jar - HQ650, DRIVE CYLINDER - Y51125 - (MPI Inspection), Jar - HQ650, KELLY STABILIZER - Y93023 - (MPI Inspection), Jar - HQ650, KNOCKER - Y48490 - (MPI Inspection), Hydra Jar - KELLY MANDREL (BLANK) (ARMACOR) HYDRA JAR 6-1/2" O.D. - OSCA289085 - (MPI Inspection), Jar - HQ650, DETENT MANDREL - AD10176 - (MPI Inspection), Jar - HQ650, LOWER FLEX JOINT, NC50 (4.5IF) PIN - AE23708 - (MPI Inspection)	5	WCD_BDT_05JUN24		BDT	PT. SMITH TOOL INDONESIA
5-Jun-24	Manggar Base	17:00-22:00	Inspected of Hydra Jar - JAR, ACCELERATOR - 6-1/2 OD -- DACCH 86123H (SL-1) - (MPI Inspection)	5	WCD_BDT_07JUN24_SL1 JAR & ACC 650		BDT	
			Inspected of Bullnose - BULLNOSE REVERSE JETS - 6-1/2 OD - AH34390 - (MPI Inspection)		Bullnose - BULLNOSE REVERSE JETS - 6-1/2 OD - AH34390		BDT	
7-Jun-24	Manggar Base	17:00-22:00	Inspected of Under Reamer - RHINO XS, UNDERREAMER - 8000 - 10544689-1, (MPI Inspection), Reamer - RHINO REAMER SPRING RETAINER 8000 - R02760 (MPI Inspection), Reamer - RHINO REAMER XS PISTON 8000 - 10376214 (MPI Inspection), Reamer - RHINO REAMER XS DRIVE RING 8000 - AJ20637 (MPI Inspection), Reamer - RHINO REAMER STOP RING 8000 - NN (MPI Inspection), Reamer - RHINO REAMER UPPER CAP 8000 - R59243 (MPI Inspection), Reamer - Inner Mandrel - 10444808-005 (MPI Inspection)	5	WCD_BDT_06JUN24_RR8000_9150627-002		BDT	
9-Jun-24	Manggar Base	17:00-22:00	Inspected of Reamer XC - CAM SUB 8.000 - AJ96655 - (MPI Inspection), Reamer XC - Lower Mandrel Sleeve 8.000 - AJ04242 - (MPI Inspection), Reamer XC - Lower Mandrel 8.000 - 8854587-003 - (MPI Inspection), Reamer XC - Valve Piston 8.000 - NA - (MPI Inspection), Reamer XC - CAM Piston / Spider CAM 8.000 - AJ16898 - (MPI Inspection), Reamer XC - Spring 8.000 - 9 - (MPI Inspection), Reamer XC - CAM Mandrel 8.000 - AK49581 - (MPI Inspection), Reamer XC - CAM Mandrel Cap 8.000 - AD24770 - (MPI Inspection), Reamer XC - Coupling 8.000 - 9209929-003 - (MPI Inspection), Reamer XC - Screen Sleeve 8.000 - AJ97598 - (MPI Inspection), Reamer XC Ring - 8.000 - AK27788 - (MPI Inspection), Reamer XC Ring - 8.000 - AK08536 - (MPI Inspection), Reamer XC Ring Cover - 8.000 - AE24938 - (MPI Inspection)	5	WCD_BDT_01JUN24_XC8000		BDT	
TOTAL (hours)				33				

Saftiadi Akbar, Rifaldi
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

19 JUN 24
 ON BEHALF: RIDWAN S.
 SLB Maintenance Supervisor