

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:	<u>Hajili, Yanuar, Mugianto</u>	Customer:	<u>PT.Schlumberger Indonesia - D&amp;M</u>	Date :	<u>3-Apr-24</u>
Period:	<u>21 Mar Thru 20 Apr 2024</u>	Contract/ PO Non:	<u>-</u>	Our Ref:	<u>-</u>
Day Rate:	<u></u>	Rig / Well:	<u>CIB</u>		
Per Diem Rate :	<u></u>			Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY (TOOL NAME_SN#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_E Machine Shop	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
1-Apr-24	CIB	16.30 - 23.00	Telescope Collar - MDCIX-MA, 8-1/4 M10 HF NON-IWOB COLLAR, INT. ALIGN. KEY, BOX x BOX, NO R.O.P. - 8A566B5 (Inspected)		WCM_020424_01		D&M	
			Telescope Collar - MDCIX-GA, 8-1/4 HF IWOB COLLAR, INT. ALIGN. KEY, BOX x BOX, NO R.O.P - N004666 (Inspected)					
			ARC Collar - DRILL COLLAR ASSY, 8.25 ARC W/O AIM RECEIVER - V6456 (Inspected)					
			Lifting Sub - Lift Sub, >=8"OD, Steel - 658F005_5 (Inspected)					
			X-Over - Lifting Box Box 6 5/8 reg x 6 5/8 FH , STEEL - SBD 9815 ((Inspected)					
<b>TOTAL (hours)</b>								

Yanuar, Mugianto  
ISP Personnel In Attendance

Hajili  
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor