


**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**




Personnel In Attendance: Mangiring, Rifaldi, Deny, Akbar, Jeremia  
 Period: Sep-23  
 Day Rate:                       
 Per Diem Rate:                     

Customer: PT DOWELL ANADRILL SCHLUMBERGER  
 Contract/ PO Non:                       
 Rig / Well: Manggar Base

Date:                                       
 Our Ref:                                       
 Form No.:                                     

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
16-Sep-23	Manggar Base	08.00 - 12.00	MSSB - CROSSOVER, M10, 5-1/2 IF PIN X 6-5/8 FH PIN - BKS 24404-0102 - Ex Machine Shop	8	WCM_AR MSSB-MC BKS 24404-0102_16Sep23		DNM	 Doni Rijantoss
OT		13.00 - 17.00	NB Stabilizer - Stabilizer, >=8" OD Body, Near Bit, Steel, Integral Spiral Blade - 12 1/8_GP 7034-16 - Inspection		To Be Created			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 17 1/4_GP 7034-108 - Inspection		To Be Created			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 14 3/4_GP 6924-28 - Inspection		To Be Created			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 17 1/4_GP 7034-3 - Inspection		To Be Created			
			String Stabilizer - Stabilizer, >=8" OD Body, String, Steel, Integral Spiral Blade - 12 1/8_RIB11-187-SBDS - Inspection		To Be Created			
			String Stab GP 7034-144 - Inspection		To Be Created			
			Stator 962 - STATOR TUBE, 962OD785ID228LG, THREADED - 20015 W0RLD3D4 - Inspection		RelineStator_16Sep23			
			Stator 675 - STATOR TUBE, 675OD550ID194LG, THREADED - 1224612 H0 - Inspection		RelineStator_16Sep23			
			Stator 675 - STATOR TUBE, 675OD550ID194LG, THREADED - 22032 W0 - Inspection		RelineStator_16Sep23			
			Stator - STATOR TUBE, 962OD785ID228LG, THREADED - 5220_TUBE - Inspection		RelineStator_16Sep23			
			Stator 962 - STATOR TUBE, 962OD785ID228LG, THREADED - 15386B0B1D2 - Inspection		RelineStator_16Sep23			
			Stator 962 - STATOR TUBE, 962OD785ID228LG, THREADED - 14074W0B1B2D3 - Inspection		RelineStator_16Sep23			
			Shaft Coupling - SHAFT COUPLING, A962M MOTOR - FP96BH1592 - Inspection		ExtraMotorParts_15Sep23			
			DV6ME - UPPER FLOW DIVERTER ASSY - UP0063 - Inspection		LWD-ET_DV6ME#1772_16Sep23			
			DV6ME - LOWER FLOW DIVERTER - LO 0309 - Inspection		LWD-ET_DV6ME#1772_16Sep23			
			DV6ME - 800 GPM FLOW TUBE ASSY - 1772 - Inspection		LWD-ET_DV6ME#1772_16Sep23			
<b>TOTAL (hours)</b>				<b>8</b>				

\* If Applicable

  
 Mangiring, Rifaldi, Deny, Akbar, Jeremia  
 Personnel In Attendance

  
 Mangiring  
 ISP Inspector

SLB Maintenance Technician

  
 Doni Rijantoss  
 SLB Maintenance Supervisor