

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Overtime)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
3-Jun-24	Manggar Base	17:00-22:00	Inspected of Reamer - Catcher - 9395118-002, - (MPI Inspection), Reamer - Catcher Cap - 9395144-011 - (MPI Inspection), Reamer - Lower mandrel - 9501375-004 - (MPI Inspection), Reamer - Lower Mandrel Cap - 9530579-002 - (MPI Inspection), Reamer - Bore Guide sleeve - 9444265-008 - (MPI Inspection), Reamer - Activation Sleeve - 9395138-009 - (MPI Inspection), Reamer - Deactivation Outer Sleeve - 9395149-010 - (MPI Inspection), Reamer - Deactivation Inner Sleeve - 9530577-001 - (MPI Inspection), Ball guide sleeve - 5000226532-8 - (MPI Inspection), Jar - Lower Detent Cylinder - AH38610 - (MPI Inspection), Jar - CONNECTOR SUB;HJ65;HB - AJ12290- (MPI Inspection)	5	WCD_BDT_08JUN24_NEW RHINO		BDT	PT. SMITH TOOL INDONESIA
TOTAL (hours)				5				

* If Applicable

Saftiadi, Rifaldi, Jeremiah
 Personnel In Attendance

Saftiadi
 ISP Inspector

Geosha
 SLB Maintenance Technician

ON BEHALF: ROMAN S.
 SLB Maintenance Supervisor

19 JUN '24