PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:	Mangiring, Deny, Dipo, Frans, Sarwo	Customer:	PT. Schlumberger Indonesia	Date :	
Period:	Aug-23	Contract/ PO Non:		Our Ref:	
Day Rate:		Rig / Well:	Manggar Base		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
3-Aug-23	Manggar Base	18.00 - 22.00	Ecoscope Collar - DV6M DRILL COLLAR - 2951R - Inspection	4	WCM_030823_DV6MC_2951R		DNM	
OT			Ecoscope Collar - DV6M DRILL COLLAR - 1705A - Inspection		WCM_030823_DV6MC_1705A			
			Float Sub - Float Sub, >=8"OD, Steel Box by Box connection; 6 5/8 RB x 6 5/8 RB ; float bore 5F/6R - RIB14-024-BBS - Inspection		To Be Created			
								ERAN A
			TOTAL (hours)	4				

* If Applicable

Mangiring, Deny, Dipo, Frans, Sarwo
Personnel In Attendance

Mangiring
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor