

PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance:

Novied Nazar, Idham

Customer:

Pertamina Hulu Kalimantan Timur

Date :

7-Mar-24

Period:

February - March 2024

Contract/ PO Non:

Day Rate:

Rig / Well:

SAPI, SEPINGGAN

Our Ref:

IR-27022024-MJM01-PHKT-SAPI-DRL
IR-22022024-MJM01-PHKT-SEPINGGAN-DRL
IR-02032024-MJM01-PHKT-SAPI-DRL

Per Diem Rate :

Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
27-Feb-24	Mulia Jaya Mandiri - Balikpapan	08.00 - 08.00	*Inspection 9-5/8" Casing Vam-21 L.80 47 PPF Pin x Box (Full Joint) Cut & Thread to become : #9-5/8" Casing Cam-21 L.80 47 PPF Box x TSH-B Pin 47 ppf -REAMER SHOE 9-5/8" X 12" DV-B. TB L-80 TSH-B EX. PT. SAGA TRADE (BLANK) Note : Make a new thread TSH-Blue Box L.80 47 PPF *Inspection CROSSOVER FLANGE 2-1/16" 5 K RX 24 RING GROOVE X 2" WECO - Break Out Connection of : PACK OFF RUNNING AND RETRIVING TOLLS WITH Pn. SP-51-22538 Break Out the X.Over 4-1/2" IF PIN x 3-1/2" TSH Blue Box *Inspection 13-3/8 Unihead, after Add Lock Ring View Port OD 0.690" ½ API LP 14 THDS,	1		
1-Mar-23	Mulia Jaya Mandiri - Balikpapan	08.00 - 20.00	*Inspection ELBOW WITH FLANGE 2-1/16" RX 24 5 K (NEWLY) X FLANGE 2-1/16" RX 24 5 K (NEWLY) *Inspection ELBOW WITH CONNECTION WECO 1502 FEMALE (EXIST) X FLANGE 2-1/16" RX 24 5 K (NEWLY)	1		
2-Mar-23	Mulia Jaya Mandiri - Balikpapan	08.00 - 22.00	*Inspection 7-1/4" OD CROSSOVER FLANGE RX 35 5K (AFTER REPAIR) X DSHT 55 BOX CONNECTION (AFTER REPAIR) *Inspection PUP JOINT 9-5/8" OD 53.50PPF, P110 TSH BLUE PIN (EXIST) X TSH BLUE PIN (NEWLY) CONNECTION, ALTERNATIVE DRIFT (8.500" OD DIA) LENGTH 6FT *Inspection 7-1/4" OD CROSSOVER SUB W/ NC 50 BOX TOP X DSHT 55 PIN BTM (AFTER REPAIR) CONNECTION	1		
TOTAL (Days)				3		
TOTAL (USD)						
GRAND TOTAL						



Novied Nazar

Inspector

Personnel In Attendance

Contractor Representative

Rig Representative

Nuhagus Kamil Chakim

Sr. Engineer Drilling Ops & QAQC Coord

The Company Representative